



NOx Analyzer Zero Drift Behavior in EPAAct/V2/E-89


NOx Zero Drift by Date & Bag




NOx Zero Drift by Date & Bag




NOx Zero Drift by Date & Bag




NOx Zero Drift by Date & Bag



NOx Zero Drift by Date & Bag




Examination of Sample and Ambient NOx



CIMP, F150, FFOC, SOUT and TCOR have >50% ambient zeros (presumably defined as a reading <0.0005)

Examination of Sample and Ambient NOx



Conclusions on NOx Zero Drift Behavior

- Zero drift does not appear to follow a predictable pattern between bags or over the course of a day
 - Most likely explanation is increased noise in analyzer electronics, suggestive of component malfunction or failure (as opposed to true systematic “drift” in signal)
 - Analyzer has been rebuilt since program data was taken, including replacement of optics and circuit boards associated with measurement reliability
 - No information is available on whether the analyzer continues to exhibit drift behavior
- It’s unclear whether the drift measurement taken at the end of each phase (shown in the plots) is representative of the measurement process during the preceding bag reads
 - Trying to correct the data may not improve precision of measurements significantly