

U.S. ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, DC

_____)	
In the Matter of:)	
)	
Doosan Infracore America Corporation and)	SETTLEMENT AGREEMENT
)	
Doosan Infracore Co., Ltd.,)	AED/MSEB #7868
)	
Respondents.)	
_____)	

This Settlement Agreement is made and entered into by and between the United States Environmental Protection Agency (EPA), and Doosan Infracore America Corporation a New York corporation, with principle business office located at 2905 Shawnee Industrial Way, Suwanee, Georgia, and Doosan Infracore Co., Ltd., a Korean corporation, with principle business office located at 7-11, Hwasu-Dong, Dong-Gu, Incheon, Korea (Respondents), to resolve allegations of non-compliance by Respondents with the requirements of Sections 203 and 213 of the Clean Air Act (Act), 42 U.S.C. §§ 7522 and 7547, and the regulations promulgated thereunder at 40 C.F.R. Part 89.

Purpose

1. The purpose of this Settlement Agreement (Agreement) is to resolve any and all claims by EPA under the Act and the regulations governing the Control of Emissions from New and In-Use Nonroad Compression-Ignition Engines, codified at 40 C.F.R. Part 89, arising out of the manufacture and/or importation of 322 engines (Subject Engines), while ensuring that future violations are avoided.

Definitions

2. For the purposes of this Agreement, the following definitions apply:

- a. *This matter*: as used in this agreement means Respondents' manufacture and/or importation of the Subject Engines and any civil liability that may apply to such violations.
- b. *Certificate of Conformity*: the document issued by EPA to a manufacturer of nonroad compression ignition engines under 40 C.F.R. § 89.105, after EPA has determined that the manufacturer's application is complete and that the test engine meets the standards of 40 C.F.R. Part 89 and the Act. Issuance of the Certificate of Conformity permits the importation and/or entry into commerce in the United States of engines built in accordance with the manufacturer's application.
- c. *Dates of the Applicable Regulations*: For nonroad compression-ignition engines rated greater than or equal to 37 kW but less than 75 kW, the applicable effective date is January 1, 1998. For nonroad compression-ignition engines rated greater than or equal to 75 kW but less than 130 kW, the applicable effective date is January 1, 1997.

Statutory and Regulatory Authority

3. Section 203(a)(1) of the Act, 42 U.S.C. § 7522(a)(1), prohibits a manufacturer from selling, offering for sale, introducing, delivering for introduction into commerce, or importing any vehicle or engine after the applicable effective date of the regulations unless such vehicle or engine is covered by a certificate of conformity issued by EPA. Section 203(a)(1) also prohibits any person or entity from causing such actions.
4. Section 213(d) of the Act, 42 U.S.C. § 7547(d), states that nonroad vehicle and engine standards shall be enforced in the same manner as the standards prescribed under Section

7521 (emission standards for new motor vehicles or new motor vehicle engines) and that the EPA has authority to revise or promulgate regulations as may be necessary to determine compliance with, and enforce, the nonroad vehicle and engine standards.

5. 40 C.F.R. § 89.105 requires every manufacturer of a new nonroad compression-ignition engine to obtain a certificate of conformity covering the engine family. The certificate of conformity must be obtained prior to selling, offering for sale, introducing into commerce, or importing into the United States the new nonroad compression-ignition engine for each model year.
6. 40 C.F.R. § 89.110 prohibits any person from manufacturing or importing into the United States any nonroad compression-ignition engine manufactured after the applicable effective date of the regulations, unless such engine bears a permanent and legible emission control information label identifying each nonroad engine. The label must contain the full corporate name and trademark of the manufacturer.
7. 40 C.F.R. § 89.2 defines engine manufacturer as any person engaged in the manufacturing or assembling of new nonroad engines or importing such engines for resale, or who acts for and is under the control of any such person in connection with the distribution of such engines.

Background

8. Respondents manufactured and/or imported 322 nonroad compression-ignition engines on the dates and as described in the Subject Engine Table which is Attachment 1 to this Settlement Agreement. The Subject Engines were sold and distributed to consumers.
9. The Subject Engines were not covered by certificates of conformity and they lacked proper EPA emission control information labels. Respondents are the manufacturers and

the importers of the Subject Engines and the nonroad equipment containing the Subject Engines.

10. The Subject Engines were manufactured after the Dates of the Applicable Regulations.
11. The Subject Engines were not covered by certificates of conformity, in violation of Section 203(a) of the Act, 42 U.S.C. § 7522(a), and 40 C.F.R. § 89.105.
12. The Subject Engines did not bear proper emission control information labels, in violation of Section 213(d) of the Act, 42 U.S.C. § 7547(d), and 40 C.F.R. § 89.110.
13. Based on the foregoing information, EPA alleges that Respondents are liable for 322 violations of Section 203(a) of the Act, 42 U.S.C. § 7522(a), and the Regulations at 40 C.F.R. § 89.105, arising from the Respondents' manufacturer, importation and distribution of the Subject Engines that were not covered by a certificate of conformity. Pursuant to Section 205 of the Act, 42 U.S.C. § 7524, Respondents are liable for a civil penalty for each of the violations.
14. Based on the foregoing information, EPA alleges that Respondents are liable for 322 violations of Section 213(d) of the Act, 42 U.S.C. § 7547(d), and the Regulations at 40 C.F.R. § 89.110, arising from the Respondents' manufacture, importation and distribution of the Subject Engines that did not bear proper emission labels. Pursuant to Section 205 of the Act, 42 U.S.C. § 7524, Respondents are liable for a civil penalty for each of the violations.

Terms

15. **Manufacturer Letter Regarding Information on Label.** Respondents will send a letter (Manufacturer Letter) to each and every owner of a Subject Engine notifying them of: 1) the incorrect or missing information on the engine label; and 2) information about

warranty coverage. The information in the Manufacturer Letter shall include that the label on the Subject Engine contains the wrong manufacturer code and shall provide information identifying the correct manufacturer, including how to contact the manufacturer. The information in the Manufacturer Letter shall also include a representation that each of the Subject Engines is covered by the warranty required by the Act and that the warranty is for five (5) years or 300 hours of operation from the date of engine manufacture, whichever occurs first. Respondents shall send the Manufacturer Letter to the engine owners on or before the date which is ninety days after the effective date of this Settlement Agreement. Respondents, at the time it issues the Manufacturer letter, shall also send a copy of the Manufacturer Letter to EPA. Within ninety days after the effective date of this Settlement Agreement, Respondents shall submit to EPA, a statement, upon penalty of perjury, that it has sent the Manufacturer Letter to all of the engine owners containing the information required by this Paragraph of the Settlement Agreement and provide proof of the sending.

16. **Representation Regarding Emissions Compliance.** Upon penalty of perjury, Respondents and their undersigned representatives state: that although the Subject Engines were not covered by a certificate of conformity, each of the Subject Engines did comply with all applicable emission standards set forth in the Act; and that they acknowledge that this representation is a material basis for EPA to enter into this Settlement Agreement.
17. **Civil Penalty.** Respondents shall pay to the United States a civil penalty of \$325,000 within 30 calendar days of the effective date of this Settlement Agreement. Late payment of the civil penalty is subject to interest and fees as specified in 31 U.S.C. § 3717.

Respondents agree to pay the amount by certified check or cashier's check payable to the "United States of America," and to mail the payment to:

ATTN: AED/MSEB # 7868
U.S. Environmental Protection Agency
Fines and Penalties
Cincinnati Finance Center
26 W. Martin Luther King Dr.
Cincinnati, Ohio 45268

A photocopy of the check shall be telefaxed simultaneously to Marcia S. Ginley at the number specified in Paragraph 20. Alternatively, Respondents may affect an online payment by visiting www.pay.gov, and entering "sfo 1.1" in the "Search Public Forms" field to access the EPA Payment Form.

Stipulated Penalties

18. For failure to comply with the terms of this Agreement on a timely basis Respondents shall pay stipulated penalties to the United States as follows:
 - a. For failure to timely pay the penalty, or provide proof of such payment, pursuant to Paragraph 17, \$400 per day.
 - b. For failure to send the Manufacturer Letter or provide proof thereof, pursuant to Paragraph 15, \$500 per day.

All stipulated penalties under Paragraph 18 of this Agreement shall begin to accrue on the calendar day after performance is due, and shall continue to accrue until the calendar day compliance is achieved. Nothing herein shall prevent the simultaneous accrual of separate stipulated penalties for separate violations of this Agreement. All stipulated penalties shall be paid in accordance with Paragraph 18 and shall be paid within five days of written demand by EPA. Stipulated penalties shall not be construed as prohibiting,

altering, or in any way limiting the ability of EPA from seeking any other remedy or sanction available by virtue of Respondents' violation of this Agreement or of the statutes or regulations upon which the Agreement is based.

General Provisions

19. This agreement does not preclude any other action by EPA for violations that are not part of this Agreement, or any future violations of the Act or regulations promulgated thereunder.

20. A copy of all correspondence and certification to EPA concerning this Agreement shall be sent to:

Marcia S. Ginley
Attorney for EPA
OECA/AED/Western Field Office (8MSU)
1595 Wynkoop Street
Denver, Colorado 80202

Tel: 303-312-7156
Fax: 303-312-6007
Email: ginley.marcia@epa.gov

21. This Agreement becomes effective upon the date executed by EPA (effective date of the Agreement), at which time a copy will be returned to Respondents.

22. Respondents hereby represent that the individual or individuals executing this Agreement on behalf of Respondents are authorized to do so on behalf of Respondents and that such execution is intended and is sufficient to bind Respondents, their agents, assigns, and successors.

23. Notwithstanding any other provision of this agreement, upon Respondents' failure to perform, or default, or failure to comply with any terms of this Agreement, EPA may refer this matter to the United States Department of Justice to recover civil penalties

pursuant to Section 205 of the Act, 42 U.S.C. § 7524, and pursue any other remedies available to it. Respondents specifically agree that in the event of such default or failure to comply, EPA may proceed in an action based on the original claim of violation of the Act and 40 C.F.R. Part 89. Respondents expressly waive their right to assert that such action is barred by any applicable statute of limitation. Respondents acknowledge that their tax identification number may be used for the purpose of collecting or reporting any delinquent monetary obligation arising from this ASA. (See 31 U.S.C. § 7701.)

24. This settlement is conditioned upon the truthfulness, accuracy and completeness of Respondents' disclosures and representations to EPA under this Agreement, and the prompt and complete remediation of any violations in accordance with this Agreement.
25. Upon completion of the terms of this Agreement, the alleged violations described in this Agreement shall be deemed terminated and resolved. Nothing herein shall limit the right of EPA to proceed against Respondents: (a) in the event of default or noncompliance with this Agreement; (b) for other violations of law; or (c) with respect to other matters not within the scope of the Agreement. This Agreement in no way affects or relieves Respondents of their responsibility to comply with other state, federal, or local laws or regulations, and does not address Respondents' potential liability to any other federal agency.

Settlement Agreement In the Matter of Doosan Infracore America Corporation et al.

U.S. Environmental Protection Agency

By: 

Date: 3/17/10

for Phillip A. Brooks, Director
Air Enforcement Division
Office of Enforcement and Compliance Assurance

ATTACHMENT 1 – Subject Engine Table

© Sales numbers of C5A Family

Model Year	E/G model	Sales numbers
2005	DB58TIS	160
2006	ditto	143
2006	ditto	19
Total		322

No.	No.	Vehicle Model	Engine Model	Vehicle S/N	Engine S/N	E/G assembly	Korea Ship	Receive Date
1	1	S14L5D	DB58TIS	DHKHEBC0K40001287	DB58TIS5?	2005-02-12	2005-02-28	2005-04-19
2	2	S14L5D	ditto	DHKHEBC0T40001326	DB58TIS5?	2005-02-28	2005-03-11	2005-05-05
3	3	S14L5D	ditto	DHKHEBC0P40001511	DB58TIS5?	2005-06-30	2005-07-25	2005-09-16
4	4	S14L5B	ditto	DHKHEBC0P40001511	DB58TIS5?	2005-06-30	2005-07-25	2005-09-06
5	5	S14L5B	ditto	DHKHEBC0V40001280	DB58TIS500558EH	2005-02-01	2005-02-28	2005-04-07
6	6	S14L5B	ditto	DHKHEBC0H40001288	DB58TIS500818EH	2005-02-12	2005-02-28	2005-04-20
7	7	S14L5B	ditto	DHKHEBC0S40001281	DB58TIS500825EH	2005-02-02	2005-02-28	2005-04-18
8	8	S14L5D	ditto	DHKHEBC0A40001308	DB58TIS500925EH	2005-02-18	2005-03-11	2005-05-05
9	9	S14L5B	ditto	DHKHEBC0L40001299	DB58TIS501036EH	2005-02-16	2005-03-28	2005-04-12
10	10	S14L5B	ditto	DHKHEBC0S40001300	DB58TIS501063EH	2005-02-16	2005-03-28	2005-04-12
11	11	S14L5D	ditto	DHKHEBC0T40001309	DB58TIS501101EJ	2005-02-18	2005-03-04	2005-04-11
12	12	S14L5D	ditto	DHKHEBC0H40001310	DB58TIS501103EH	2005-02-19	2005-03-04	2005-04-11
13	13	S14L5C	ditto	DHKHEBC0E40001334	DB58TIS501120EH	2005-03-11	2005-04-04	2005-05-09
14	14	S14L5D	ditto	DHKHEBC0S40001331	DB58TIS501122EH	2005-03-10	2005-04-04	2005-05-09
15	15	S14L5B	ditto	DHKHEBC0P40001301	DB58TIS501123EH	2005-02-16	2005-03-04	2005-04-11
16	16	S14L5D	ditto	DHKHEBC0K40001323	DB58TIS501137EH	2005-02-26	2005-03-11	2005-04-22
17	17	S14L5B	ditto	DHKHEBC0S40001336	DB58TIS501183EH	2005-03-18	2005-04-04	2005-05-09
18	18	S14L5D	ditto	DHKHEBC0V40001327	DB58TIS501221EH	2005-02-28	2005-03-11	2005-05-06
19	19	S14L5C	ditto	DHKHEBC0C40001333	DB58TIS501222EH	2005-03-10	2005-04-09	2005-04-27
20	20	S14L5B	ditto	DHKHEBC0C40001302	DB58TIS501224EH	2005-02-17	2005-04-09	2005-05-12
21	21	S14L5D	ditto	DHKHEBC0H40001324	DB58TIS501259EH	2005-02-28	2005-03-11	2005-04-22
22	22	S14L5D	ditto	DHKHEBC0V40001344	DB58TIS501260EH	2005-03-23	2005-04-30	2005-06-06
23	23	S14L5D	ditto	DHKHEBC0A40001325	DB58TIS501261EH	2005-02-28	2005-03-11	2005-05-05
24	24	S14L5C	ditto	DHKHEBC0L40001335	DB58TIS501376EH	2005-03-11	2005-04-04	2005-05-11
25	25	S14L5D	ditto	DHKHEBC0P40001332	DB58TIS501378EH	2005-03-10	2005-04-09	2005-04-27
26	26	S14L5D	ditto	DHKHEBC0E40001348	DB58TIS501842EH	2005-03-30	2005-04-30	2005-06-10
27	27	S14L5D	ditto	DHKHEBC0E40001351	DB58TIS501843EH	2005-03-31	2005-04-30	2005-06-09
28	28	S14L5C	ditto	DHKHEBC0P40001346	DB58TIS501844EA	2005-03-29	2005-04-30	2005-05-31
29	29	S14L5D	ditto	DHKHEBC0L40001349	DB58TIS501845EH	2005-03-30	2005-04-30	2005-05-31
30	30	S14L5D	ditto	DHKHEBC0S40001345	DB58TIS501953EH	2005-03-28	2005-04-30	2005-05-19
31	31	S14L5C	ditto	DHKHEBC0C40001347	DB58TIS501956EH	2005-03-29	2005-04-30	2005-05-31
32	32	S14L5C	ditto	DHKHEBC0T40001360	DB58TIS502193EH	2005-04-11	2005-04-30	2005-05-31
33	33	S14L5D	ditto	DHKHEBC0K40001354	DB58TIS502196EH	2005-04-06	2005-04-30	2005-05-31
34	34	S14L5A	ditto	DHKHEBC0K40001371	DB58TIS502469EH	2005-04-16	2005-04-30	2005-06-07
35	35	S14L5D	ditto	DHKHEBC0E40001396	DB58TIS502516EH	2005-04-28	2005-05-24	2005-07-13
36	36	S14L5C	ditto	DHKHEBC0S40001359	DB58TIS502613EH	2005-04-11	2005-04-30	2005-06-03
37	37	S14L5A	ditto	DHKHEBC0C40001395	DB58TIS502791EH	2005-04-28	2005-05-21	2005-07-05
38	38	S14L5C	ditto	DHKHEBC0A40001390	DB58TIS502793EH	2005-04-26	2005-05-10	2005-06-17
39	39	S14L5D	ditto	DHKHEBC0S40001393	DB58TIS502800EH	2005-04-27	2005-05-24	2005-06-29
40	40	S14L5C	ditto	DHKHEBC0T40001391	DB58TIS502801EH	2005-04-26	2005-05-10	2005-06-29
41	41	S14L5B	ditto	DHKHEBC0V40001392	DB58TIS502803EH	2005-04-26	2005-05-10	2005-06-29
42	42	S14L5A	ditto	DHKHEBC0C40001400	DB58TIS502977EH	2005-04-29	2005-06-17	2005-07-28
43	43	S14L5C	ditto	DHKHEBC0P40001430	DB58TIS503596EH	2005-05-23	2005-06-17	2005-07-15
44	44	S14L5D	ditto	DHKHEBC0C40001431	DB58TIS503598EH	2005-05-25	2005-11-22	2006-01-06
45	45	S14L5B	ditto	DHKHEBC0A40001552	DB58TIS504320EH	2005-07-25	2005-08-17	2005-10-11
46	46	S14L5B	ditto	DHKHEBC0C40001459	DB58TIS504321EH	2005-06-10	2005-06-23	2005-08-02
47	47	S14L5B	ditto	DHKHEBC0P40001461	DB58TIS504368EH	2005-06-11	2005-06-23	2005-07-13

No.	No.	Vehicle Model	Engine Model	Vehicle S/N	Engine S/N	E/G assembly	Korea Ship	Receive Date
48	48	S14L5C	ditto	DHKHEBC0T40001469	DB58TIS504369EH	2005-06-15	2005-07-17	2005-08-23
49	49	S14L5B	ditto	DHKHEBC0C40001462	DB58TIS504371EH	2005-06-13	2005-06-23	2005-08-02
50	50	S14L5D	ditto	DHKHEBC0H40001467	DB58TIS504425EH	2005-06-14	2005-06-30	2005-08-11
51	51	S14L5B	ditto	DHKHEBC0S40001460	DB58TIS504427EH	2005-06-10	2005-06-23	2005-08-11
52	52	S14L5C	ditto	DHKHEBC0H40001470	DB58TIS504428EH	2005-06-16	2005-07-17	2005-08-23
53	53	S14L5C	ditto	DHKHEBC0T40001472	DB58TIS504600EH	2005-06-16	2005-07-25	2005-09-07
54	54	S14L5D	ditto	DHKHEBC0E40001463	DB58TIS504631EH	2005-06-13	2005-06-23	2005-08-12
55	55	S14L5D	ditto	DHKHEBC0A40001468	DB58TIS504634EH	2005-06-15	2005-06-23	2005-08-15
56	56	S14L5C	ditto	DHKHEBC0A40001471	DB58TIS504749EH	2005-06-16	2005-07-25	2005-09-06
57	57	S14L5B	ditto	DHKHEBC0P40001511	DB58TIS504793EH	2005-06-29	2005-08-17	2005-10-11
58	58	S14L5B	ditto	DHKHEBC0K40001502	DB58TIS504813EH	2005-06-25	2005-07-25	2005-08-29
59	59	S14L5D	ditto	DHKHEBC0S40001510	DB58TIS504992EH	2005-06-29	2005-11-22	2006-01-06
60	60	S14L5B	ditto	DHKHEBC0H40001503	DB58TIS505089EH	2005-06-27	2005-07-25	2005-09-06
61	61	S14L5D	ditto	DHKHEBC0H40001517	DB58TIS505498EH	2005-07-13	2005-07-25	2005-09-07
62	62	S14L5D	ditto	DHKHEBC0T40001519	DB58TIS505499EH	2005-07-13	2005-07-25	2005-09-07
63	63	S14L5B	ditto	DHKHEBC0A40001518	DB58TIS505500EH	2005-07-13	2005-07-25	2005-09-06
64	64	S14L5B	ditto	DHKHEBC0H40001548	DB58TIS505621EH	2005-07-22	2005-08-17	2005-10-06
65	65	S14L5D	ditto	DHKHEBC0H40001551	DB58TIS505646EH	2005-07-23	2005-08-17	2005-10-11
66	66	S14L5B	ditto	DHKHEBC0V40001554	DB58TIS505691EH	2005-07-25	2005-08-17	2005-10-06
67	67	S14L5B	ditto	DHKHEBC0K40001547	DB58TIS505692EH	2005-07-22	2005-08-17	2005-10-11
68	68	S14L5B	ditto	DHKHEBC0T40001553	DB58TIS505808EH	2005-07-25	2005-08-19	2005-09-21
69	69	S14L5B	ditto	DHKHEBC0S40001555	DB58TIS505809EH	2005-07-26	2005-08-19	2005-09-28
70	70	S14L5D	ditto	DHKHEBC0P50001557	DB58TIS505969EH	2005-08-11	2005-08-27	2005-09-28
71	71	S14L5C	ditto	DHKHEBC0P50001560	DB58TIS505971EH	2005-08-12	2005-08-26	2005-09-30
72	72	S14L5B	ditto	DHKHEBC0S50001556	DB58TIS506011EH	2005-08-10	2005-08-19	2005-09-28
73	73	S14L5B	ditto	DHKHEBC0C50001558	DB58TIS506012EH	2005-08-11	2005-08-19	2005-09-28
74	74	S14L5C	ditto	DHKHEBC0C50001561	DB58TIS506013EH	2005-08-12	2005-08-26	2005-10-03
75	75	S14L5D	ditto	DHKHEBC0E50001559	DB58TIS506085EH	2005-08-12	2005-08-19	2005-09-22
76	76	S14L5B	ditto	DHKHEBC0S50001581	DB58TIS506834EH	2005-09-09	2005-09-23	2005-11-08
77	77	S14L5B	ditto	DHKHEBC0K50001582	DB58TIS506878EH	2005-09-09	2005-09-23	2005-11-08
78	78	S14L5C	ditto	DHKHEBC0S50001600	DB58TIS506881EH	2005-09-22	2005-10-14	2005-11-18
79	79	S14L5C	ditto	DHKHEBC0K50001601	DB58TIS507047EH	2005-09-23	2005-10-14	2005-11-17
80	80	S14L5C	ditto	DHKHEBC0H50001602	DB58TIS507355EH	2005-09-24	2005-10-14	2005-11-17
81	81	S14L5D	ditto	DHKHEBC0K50001615	DB58TIS507421EH	2005-10-05	2005-10-24	2005-12-02
82	82	S14L5C	ditto	DHKHEBC0H50001616	DB58TIS507423EH	2005-10-05	2005-10-24	2005-12-02
83	83	S14L5A	ditto	DHKHEBC0K50001629	DB58TIS507451EH	2005-10-17	2005-10-31	2005-12-14
84	84	S14L5D	ditto	DHKHEBC0A50001620	DB58TIS507539EH	2005-10-07	2005-10-22	2005-11-23
85	85	S14L5D	ditto	DHKHEBC0S50001614	DB58TIS507542EH	2005-10-05	2005-10-22	2005-11-23
86	86	S14L5D	ditto	DHKHEBC0L50001613	DB58TIS507551EH	2005-10-05	2005-10-24	2005-12-02
87	87	S14L5D	ditto	DHKHEBC0V50001619	DB58TIS507554EH	2005-10-07	2005-10-24	2005-12-02
88	88	S14L5C	ditto	DHKHEBC0T50001618	DB58TIS507555EH	2005-10-07	2005-10-24	2005-12-16
89	89	S14L5D	ditto	DHKHEBC0H50001633	DB58TIS507744EH	2005-10-18	2005-11-15	2005-12-28
90	90	S14L5D	ditto	DHKHEBC0K50001632	DB58TIS507818EH	2005-10-17	2005-11-15	2006-01-03
91	91	S14L5A	ditto	DHKHEBC0S50001628	DB58TIS507819EH	2005-10-15	2005-10-31	2005-12-14
92	92	S14L5B	ditto	DHKHEBC0P50001638	DB58TIS507820EH	2005-10-19	2005-11-15	2005-12-29
93	93	S14L5A	ditto	DHKHEBC0L50001630	DB58TIS507821EH	2005-10-17	2005-12-01	2006-01-26
94	94	S14L5A	ditto	DHKHEBC0S50001631	DB58TIS507822EH	2005-10-17	2005-12-01	2006-01-04
95	95	S14L5B	ditto	DHKHEBC0S50001637	DB58TIS507915EH	2005-10-19	2005-11-15	2005-12-28
96	96	S14L5B	ditto	DHKHEBC0L50001644	DB58TIS507919EH	2005-10-27	2005-11-15	2006-01-03
97	97	S14L5B	ditto	DHKHEBC0E50001643	DB58TIS507963EH	2005-10-26	2005-11-15	2005-12-19
98	98	S14L5A	ditto	DHKHEBC0S50001654	DB58TIS508267EA	2005-11-14	2005-12-01	2006-01-26
99	99	S14L5D	ditto	DHKHEBC0P50001655	DB58TIS508268EH	2005-11-14	2005-11-22	2005-12-27
100	100	S14L5A	ditto	DHKHEBC0C50001656	DB58TIS508408EH	2005-11-15	2005-12-01	2006-01-04
101	101	S14L5B	ditto	DHKHEBC0V50001653	DB58TIS508409EH	2005-11-14	2005-11-22	2005-12-13
102	102	S14L5D	ditto	DHKHEBC0E50001660	DB58TIS508448EH	2005-11-16	2005-12-12	2006-01-11

No.	No.	Vehicle Model	Engine Model	Vehicle S/N	Engine S/N	E/G assembly	Korea Ship	Receive Date
103	103	S14L5A	ditto	DHKHEBC0S50001659	DB58TIS508449EF	2005-11-16	2005-12-20	2006-02-15
104	104	S14L5D	ditto	DHKHEBC0E50001657	DB58TIS508451EA	2005-11-16	2005-11-22	2006-01-06
105	105	S14L5A	ditto	DHKHEBC0L50001661	DB58TIS508522EH	2005-11-17	2005-12-20	2006-02-15
106	106	S14L5B	ditto	DHKHEBC0A50001665	DB58TIS508523EH	2005-11-22	2005-12-20	2006-02-14
107	107	S14L5B	ditto	DHKHEBC0T50001666	DB58TIS508525EH	2005-11-22	2005-12-20	2006-02-14
108	108	S14L5D	ditto	DHKHEBC0H50001664	DB58TIS508571EH	2005-11-21	2005-12-20	2006-02-15
109	109	S14L5D	ditto	DHKHEBC0S50001671	DB58TIS508572EH	2005-11-24	2005-12-12	2006-01-11
110	110	S14L5D	ditto	DHKHEBC0V50001667	DB58TIS508573EH	2005-11-23	2005-12-20	2006-02-14
111	111	S14L5D	ditto	DHKHEBC0P50001669	DB58TIS508610EH	2005-11-24	2005-12-20	2006-02-07
112	112	S14L5D	ditto	DHKHEBC0K50001677	DB58TIS508688EH	2005-11-30	2005-12-23	2006-02-02
113	113	S14L5D	ditto	DHKHEBC0E50001674	DB58TIS508752EH	2005-11-29	2005-12-23	2006-02-01
114	114	S14L5D	ditto	DHKHEBC0K50001680	DB58TIS509043EH	2005-12-09	2005-12-26	2006-01-23
115	115	S14L5D	ditto	DHKHEBC0T50001683	DB58TIS509045EH	2005-12-10	2005-12-23	2006-02-01
116	116	S14L5D	ditto	DHKHEBC0H50001695	DB58TIS509103EH	2005-12-20	2006-01-14	2006-02-09
117	117	S14L5D	ditto	DHKHEBC0A50001696	DB58TIS509262EH	2005-12-20	2006-01-14	2006-02-09
118	118	S14L5B	ditto	DHKHEBC0T50001697	DB58TIS509299EH	2005-12-20	2006-01-23	2006-03-22
119	119	S14L5B	ditto	DHKHEBC0V50001698	DB58TIS509393EH	2005-12-21	2006-01-23	2006-03-22
120	120	S14L5C	ditto	DHKHEBC0A60001702	DB58TIS509549EH	2006-01-04	2006-01-27	2006-03-07
121	121	S14L5C	ditto	DHKHEBC0V60001699	DB58TIS509656EH	2006-01-04	2006-01-27	2006-03-10
122	122	S14L5B	ditto	DHKHEBC0E60001708	DB58TIS509775EH	2006-01-18	2006-01-27	2006-03-07
123	123	TXC140-1	ditto	30035	DB58TIS5?	2005-02-23		
124	124	TXC140-1	ditto	30036	DB58TIS5?	2005-02-24		
125	125	TXC140-1	ditto	30037	DB58TIS5?	2005-02-24		
126	126	TXC140-1	ditto	30038	DB58TIS5?	2005-02-24		
127	127	TXC140-1	ditto	30039	DB58TIS503106EH	2005-05-10		
128	128	TXC140-1	ditto	30040	DB58TIS504162EH	2005-07-07		
129	129	TXC140-1	ditto	30041	DB58TIS504792EH	2005-07-07		
130	130	TXC140-1	ditto	30043	DB58TIS504794EH	2005-07-08		
131	131	TXC140-1	ditto	30046	DB58TIS505009EH	2005-08-08		
132	132	TXC140-1	ditto	30044	DB58TIS505010EH	2005-08-08		
133	133	TXC140-1	ditto	30042	DB58TIS505393EH	2005-07-08		
134	134	TXC140-1	ditto	30045	DB58TIS505810EH	2005-08-08		
135	135	TXC140-1	ditto	30048	DB58TIS506652EH	2005-09-02		
136	136	TXC140-1	ditto	30047	DB58TIS506653EH	2005-09-02		
137	137	TXC140-1	ditto	30052	DB58TIS506748EH	2005-09-07		
138	138	TXC140-1	ditto	30051	DB58TIS506749EH	2005-09-07		
139	139	TXC140-1	ditto	30050	DB58TIS506750EH	2005-09-05		
140	140	TXC140-1	ditto	30049	DB58TIS506752EH	2005-09-05		
141	141	TXC140-1	ditto	30053	DB58TIS506838EH	2005-09-08		
142	142	TXC140-1	ditto	30057	DB58TIS506947EH	2005-09-28		
143	143	TXC140-1	ditto	30056	DB58TIS507051EH	2005-09-28		
144	144	TXC140-1	ditto	30069	DB58TIS507079EH	2005-12-08		
145	145	TXC140-1	ditto	30055	DB58TIS507353EH	2005-09-28		
146	146	TXC140-1	ditto	30054	DB58TIS507381EH	2005-09-27		
147	147	TXC140-1	ditto	30059	DB58TIS507450EH	2005-09-29		
148	148	TXC140-1	ditto	30058	DB58TIS507453EH	2005-09-28		
149	149	TXC140-1	ditto	30062	DB58TIS508265EH	2005-11-15		
150	150	TXC140-1	ditto	30060	DB58TIS508266EH	2005-11-15		
151	151	TXC140-1	ditto	30065	DB58TIS508324EH	2005-11-25		
152	152	TXC140-1	ditto	30061	DB58TIS508410EH	2005-11-15		
153	153	TXC140-1	ditto	30063	DB58TIS508412EH	2005-11-15		
154	154	TXC140-1	ditto	30064	DB58TIS508526EH	2005-11-25		
155	155	TXC140-1	ditto	30067	DB58TIS508574EH	2005-11-25		
156	156	TXC140-1	ditto	30066	DB58TIS508612EH	2005-11-25		
157	157	TXC140-1	ditto	30068	DB58TIS508646EH	2005-11-26		

No.	No.	Vehicle Model	Engine Model	Vehicle S/N	Engine S/N	E/G assembly	Korea Ship	Receive Date
158	158	TXC140-1	ditto	30072	DB58TIS509042EH	2005-12-13		
159	159	TXC140-1	ditto	30070	DB58TIS509080EH	2005-12-09		
160	160	TXC140-1	ditto	30071	DB58TIS509105EH	2005-12-13		
161	1	S14L5C	ditto	DHKHEBC0V60001749	DB58TIS67	2006-02-27	2006-03-31	2006-05-16
162	2	S14L5C	ditto	DHKHEBC0C60001805	DB58TIS67	2006-04-26	2006-05-17	2006-06-16
163	3	S14L5B	ditto	DHKHEBC0L60001709	DB58TIS600140EH	2006-01-18	2006-02-16	2006-04-10
164	4	S14L5B	ditto	DHKHEBC0T60001717	DB58TIS600289EH	2006-01-25	2006-02-16	2006-04-11
165	5	S14L5C	ditto	DHKHEBC0V60001718	DB58TIS600389EH	2006-02-04	2006-02-17	2006-04-06
166	6	S14L5C	ditto	DHKHEBC0S60001719	DB58TIS600747EH	2006-02-04	2006-02-17	2006-04-05
167	7	S14L5B	ditto	DHKHEBC0H60001746	DB58TIS601023EH	2006-02-22	2006-03-12	2006-05-15
168	8	S14L5B	ditto	DHKHEBC0T60001748	DB58TIS601024EH	2006-02-23	2006-03-25	2006-05-17
169	9	S14L5B	ditto	DHKHEBC0A60001747	DB58TIS601090EH	2006-02-23	2006-03-12	2006-05-15
170	10	S14L5D	ditto	DHKHEBC0P60001737	DB58TIS601131EH	2006-02-19	2006-03-12	2006-05-10
171	11	S14L5B	ditto	DHKHEBC0S60001744	DB58TIS601132EH	2006-02-21	2006-03-12	2006-05-10
172	12	S14L5B	ditto	DHKHEBC0K60001745	DB58TIS601385EH	2006-02-22	2006-03-12	2006-05-15
173	13	S14L5D	ditto	DHKHEBC0T60001751	DB58TIS601388EH	2006-02-28	2006-03-20	2006-05-12
174	14	S14L5C	ditto	DHKHEBC0A60001750	DB58TIS601587EH	2006-02-28	2006-03-31	2006-05-23
175	15	S14L5D	ditto	DHKHEBC0C60001755	DB58TIS601701EH	2006-03-10	2006-03-25	2006-05-23
176	16	S14L5D	ditto	DHKHEBC0K60001762	DB58TIS601876EH	2006-03-20	2006-03-31	2006-05-16
177	17	S14L5D	ditto	DHKHEBC0L60001760	DB58TIS601878EH	2006-03-18	2006-03-31	2006-05-16
178	18	S14L5B	ditto	DHKHEBC0T60001765	DB58TIS601910EH	2006-03-21	2006-03-31	2006-05-16
179	19	S14L5D	ditto	DHKHEBC0S60001758	DB58TIS601994EH	2006-03-17	2006-03-31	2006-05-16
180	20	S14L5D	ditto	DHKHEBC0A60001778	DB58TIS602027EH	2006-04-04	2006-04-18	2006-05-25
181	21	S14L5D	ditto	DHKHEBC0L60001774	DB58TIS602273EH	2006-03-27	2006-04-18	2006-05-24
182	22	S14L5B	ditto	DHKHEBC0H60001780	DB58TIS602657EH	2006-04-05	2006-04-28	2006-05-24
183	23	S14L5B	ditto	DHKHEBC0S60001820	DB58TIS602659EH	2006-05-10	2006-05-26	2006-07-14
184	24	S14L5D	ditto	DHKHEBC0L60001791	DB58TIS602741EH	2006-04-13	2006-04-29	2006-06-15
185	25	S14L5B	ditto	DHKHEBC0P60001785	DB58TIS602742EH	2006-04-12	2006-04-29	2006-06-15
186	26	S14L5B	ditto	DHKHEBC0C60001786	DB58TIS602819EH	2006-04-12	2006-04-29	2006-06-14
187	27	S14L5B	ditto	DHKHEBC0A60001781	DB58TIS602820EH	2006-04-05	2006-04-18	2006-05-30
188	28	S14L5C	ditto	DHKHEBC0L60001788	DB58TIS602821EH	2006-04-13	2006-04-29	2006-06-15
189	29	S14L5D	ditto	DHKHEBC0S60001784	DB58TIS602867EH	2006-04-12	2006-04-29	2006-06-05
190	30	S14L5D	ditto	DHKHEBC0E60001787	DB58TIS603097EH	2006-04-12	2006-04-27	2006-06-15
191	31	S14L5D	ditto	DHKHEBC0A60001800	DB58TIS603098EH	2006-04-22	2006-05-17	2006-06-22
192	32	S14L5C	ditto	DHKHEBC0P60001799	DB58TIS603099EH	2006-04-17	2006-05-17	2006-06-16
193	33	S14L5B	ditto	DHKHEBC0H60001794	DB58TIS603101EH	2006-04-14	2006-05-23	2006-07-06
194	34	S14L5C	ditto	DHKHEBC0S60001789	DB58TIS603200EH	2006-04-13	2006-04-29	2006-06-20
195	35	S14L5C	ditto	DHKHEBC0T60001801	DB58TIS603222EH	2006-04-24	2006-05-17	2006-06-14
196	36	S14L5B	ditto	DHKHEBC0V60001797	DB58TIS603225EH	2006-04-17	2006-05-17	2006-06-27
197	37	S14L5B	ditto	DHKHEBC0S60001798	DB58TIS603270EH	2006-04-17	2006-05-17	2006-07-05
198	38	S14L5D	ditto	DHKHEBC0S60001803	DB58TIS603521EH	2006-04-24	2006-05-17	2006-06-28
199	39	S14L5C	ditto	DHKHEBC0S60001808	DB58TIS603523EH	2006-04-26	2006-05-17	2006-06-16
200	40	S14L5D	ditto	DHKHEBC0E60001806	DB58TIS603525EH	2006-04-26	2006-05-23	2006-07-05
201	41	S14L5D	ditto	DHKHEBC0L60001841	DB58TIS603535EH	2006-05-22	2006-06-23	2006-08-15
202	42	S14L5C	ditto	DHKHEBC0P60001804	DB58TIS603537EH	2006-04-25	2006-05-17	2006-06-21
203	43	S14L5C	ditto	DHKHEBC0L60001807	DB58TIS603672EH	2006-04-26	2006-05-17	2006-06-16
204	44	S14L5C	ditto	DHKHEBC0K60001809	DB58TIS603673EH	2006-05-02	2006-05-17	2006-06-16
205	45	S14L5D	ditto	DHKHEBC0A60001814	DB58TIS603674EH	2006-05-04	2006-05-26	2006-07-10
206	46	S14L5C	ditto	DHKHEBC0V60001802	DB58TIS603675EH	2006-04-24	2006-05-17	2006-06-16
207	47	S14L5D	ditto	DHKHEBC0C60001822	DB58TIS603789EH	2006-05-11	2006-05-27	2006-06-22
208	48	S14L5C	ditto	DHKHEBC0S60001811	DB58TIS603950EH	2006-05-03	2006-05-26	2006-07-07
209	49	S14L5B	ditto	DHKHEBC0T60001815	DB58TIS603951EH	2006-05-04	2006-05-17	2006-06-27
210	50	S14L5D	ditto	DHKHEBC0L60001810	DB58TIS603952EH	2006-05-02	2006-05-17	2006-06-22
211	51	S14L5B	ditto	DHKHEBC0V60001816	DB58TIS603953EH	2006-05-04	2006-05-17	2006-06-27
212	52	S14L5B	ditto	DHKHEBC0P60001821	DB58TIS603954EH	2006-05-10	2006-05-26	2006-07-10

No.	No.	Vehicle Model	Engine Model	Vehicle S/N	Engine S/N	E/G assembly	Korea Ship	Receive Date
213	53	S14L5B	ditto	DHKHEBC0T60001829	DB58TIS604100EH	2006-05-14	2006-05-26	2006-07-14
214	54	S14L5D	ditto	DHKHEBC0C60001819	DB58TIS604101EH	2006-05-10	2006-05-19	2006-06-15
215	55	S14L5B	ditto	DHKHEBC0L60001824	DB58TIS604102EH	2006-05-12	2006-05-26	2006-07-14
216	56	S14L5B	ditto	DHKHEBC0T60001880	DB58TIS604150EH	2006-07-25	2006-08-27	2006-10-04
217	57	S14L5C	ditto	DHKHEBC0V60001833	DB58TIS604151EH	2006-05-16	2006-06-19	2006-07-20
218	58	S14L5B	ditto	DHKHEBC0E60001823	DB58TIS604152EH	2006-05-11	2006-05-26	2006-07-10
219	59	S14L5D	ditto	DHKHEBC0S60001825	DB58TIS604221EH	2006-05-12	2006-05-27	2006-06-15
220	60	S14L5D	ditto	DHKHEBC0A60001831	DB58TIS604288EH	2006-05-16	2006-05-26	2006-07-06
221	61	S14L5B	ditto	DHKHEBC0H60001827	DB58TIS604310EH	2006-05-12	2006-05-26	2006-07-10
222	62	S14L5B	ditto	DHKHEBC0K60001826	DB58TIS604336EH	2006-05-12	2006-05-26	2006-07-11
223	63	S14L5D	ditto	DHKHEBC0A60001828	DB58TIS604337EH	2006-05-14	2006-05-26	2006-07-12
224	64	S14L5B	ditto	DHKHEBC0A60001845	DB58TIS604338EH	2006-05-23	2006-06-19	2006-07-24
225	65	S14L5C	ditto	DHKHEBC0C60001836	DB58TIS604339EH	2006-05-18	2006-06-19	2006-08-03
226	66	S14L5C	ditto	DHKHEBC0T60001832	DB58TIS604374EH	2006-05-16	2006-06-19	2006-08-08
227	67	S14L5A	ditto	DHKHEBC0H60001830	DB58TIS604376EH	2006-05-15	2006-05-26	2006-07-17
228	68	S14L5D	ditto	DHKHEBC0H60001844	DB58TIS604411EH	2006-05-23	2006-06-19	2006-08-10
229	69	S14L5D	ditto	DHKHEBC0S60001834	DB58TIS604413EH	2006-05-17	2006-05-26	2006-07-12
230	70	S14L5C	ditto	DHKHEBC0L60001838	DB58TIS604414EH	2006-05-18	2006-06-19	2006-07-28
231	71	S14L5C	ditto	DHKHEBC0P60001835	DB58TIS604415EH	2006-05-17	2006-06-19	2006-07-25
232	72	S14L5B	ditto	DHKHEBC0P60001849	DB58TIS604516EH	2006-05-24	2006-06-23	2006-08-15
233	73	S14L5B	ditto	DHKHEBC0S60001848	DB58TIS604518EH	2006-05-24	2006-06-30	2006-07-19
234	74	S14L5D	ditto	DHKHEBC0V60001847	DB58TIS604519EH	2006-05-24	2006-06-19	2006-08-10
235	75	S14L5C	ditto	DHKHEBC0S60001842	DB58TIS604663EH	2006-05-22	2006-06-23	2006-07-26
236	76	S14L5B	ditto	DHKHEBC0T60001846	DB58TIS604665EH	2006-05-24	2006-06-19	2006-08-09
237	77	S14L5B	ditto	DHKHEBC0E60001840	DB58TIS604666EH	2006-05-22	2006-09-29	2006-10-26
238	78	S14L5B	ditto	DHKHEBC0S60001851	DB58TIS604802EH	2006-05-29	2006-06-23	2006-08-15
239	79	S14L5D	ditto	DHKHEBC0V60001850	DB58TIS604899EH	2006-05-29	2006-06-23	2006-08-15
240	80	S14L5B	ditto	DHKHEBC0E60001854	DB58TIS604901EH	2006-05-30	2006-06-23	2006-08-15
241	81	S14L5D	ditto	DHKHEBC0C60001853	DB58TIS604971EH	2006-05-29	2006-06-30	2006-07-27
242	82	S14L5B	ditto	DHKHEBC0P60001852	DB58TIS604973EH	2006-05-29	2006-06-23	2006-08-11
243	83	S14L5B	ditto	DHKHEBC0E60001899	DB58TIS605112EH	2006-09-01	2006-09-16	2006-10-11
244	84	S14L5B	ditto	DHKHEBC0L60001869	DB58TIS605192EH	2006-06-21	2006-07-22	2006-08-25
245	85	S14L5D	ditto	DHKHEBC0S60001890	DB58TIS605193EH	2006-08-10	2006-10-31	2006-12-19
246	86	S14L5B	ditto	DHKHEBC0P60001866	DB58TIS605500EH	2006-06-20	2006-07-22	2006-08-16
247	87	S14L5C	ditto	DHKHEBC0V60001864	DB58TIS605502EH	2006-06-19	2006-07-22	2006-08-25
248	88	S14L5D	ditto	DHKHEBC0E60001868	DB58TIS605640EH	2006-06-21	2006-08-28	2006-08-30
249	89	S14L5C	ditto	DHKHEBC0T60001863	DB58TIS605643EH	2006-06-19	2006-07-24	2006-08-31
250	90	S14L5B	ditto	DHKHEBC0C60001867	DB58TIS605685EH	2006-06-21	2006-07-24	2006-09-08
251	91	S14L5B	ditto	DHKHEBC0P60001883	DB58TIS605687EH	2006-07-26	2006-08-25	2006-10-05
252	92	S14L5B	ditto	DHKHEBC0S60001882	DB58TIS605689EH	2006-07-26	2006-08-25	2006-10-05
253	93	S14L5D	ditto	DHKHEBC0S60001865	DB58TIS605722EH	2006-06-20	2006-07-24	2006-09-07
254	94	S14L5D	ditto	DHKHEBC0E60001871	DB58TIS605724EH	2006-06-22	2006-07-22	2006-08-24
255	95	S14L5B	ditto	DHKHEBC0S60001879	DB58TIS606604EH	2006-07-14	2006-09-30	2006-11-07
256	96	S14L5B	ditto	DHKHEBC0V60001881	DB58TIS606724EH	2006-07-25	2006-08-19	2006-09-13
257	97	S14L5C	ditto	DHKHEBC0L60001886	DB58TIS606919EH	2006-08-09	2006-08-25	2006-10-04
258	98	S14L5B	ditto	DHKHEBC0S60001896	DB58TIS607067EH	2006-08-14	2006-09-09	2006-10-11
259	99	S14L5B	ditto	DHKHEBC0P60001897	DB58TIS607170EH	2006-08-14	2007-03-25	2007-05-10
260	100	S14L5B	ditto	DHKHEBC0C60001903	DB58TIS607500EH	2006-09-05	2006-09-16	2006-10-11
261	101	S14L5C	ditto	DHKHEBC0P60001902	DB58TIS607503EH	2006-09-04	2006-09-30	2006-11-07
262	102	S14L5C	ditto	DHKHEBC0S60001901	DB58TIS607510EH	2006-09-04	2006-09-30	2006-11-07
263	103	S14L5B	ditto	DHKHEBC0V60001900	DB58TIS607561EH	2006-09-04	2006-09-16	2006-10-12
264	104	S14L5D	ditto	DHKHEBC0C60001920	DB58TIS607969EH	2006-09-21	2006-10-31	2006-12-19
265	105	S14L5D	ditto	DHKHEBC0S60001923	DB58TIS607971EH	2006-09-22	2007-02-11	2007-06-06
266	106	S14L5D	ditto	DHKHEBC0K60001924	DB58TIS608843EH	2006-10-17	2007-06-30	2007-07-30
267	107	S14L5B	ditto	DHKHEBC0E70001970	DB58TIS609095EH	2007-01-11	2007-01-24	2007-03-15

No.	No.	Vehicle Model	Engine Model	Vehicle S/N	Engine S/N	E/G assembly	Korea Ship	Receive Date
268	108	S14L5C	ditto	DHKHEBC0V60001931	DB58TIS609108EH	2006-10-26	2006-11-25	2007-01-05
269	109	S14L5C	ditto	DHKHEBC0S60001940	DB58TIS609181EH	2006-11-07	2006-11-25	2007-01-05
270	110	S14L5C	ditto	DHKHEBC0S60001954	DB58TIS609955EH	2006-11-27	2006-12-30	2007-01-30
271	111	S14L5C	ditto	DHKHEBC0K60001955	DB58TIS610078EH	2006-11-27	2006-12-22	2007-01-31
272	112	S14L5B	ditto	DHKHEBC0S70001964	DB58TIS610715EH	2007-01-06	2007-01-24	2007-03-16
273	113	S14L5B	ditto	DHKHEBC0V70001963	DB58TIS611237EH	2007-01-03	2007-01-24	2007-03-20
274	114	S14L5C	ditto	DHKHEBC0C70001966	DB58TIS611238EH	2007-01-08	2007-01-24	2007-03-19
275	115	S14L5B	ditto	DHKHEBC0P70001965	DB58TIS611239EH	2007-01-06	2007-01-24	2007-03-23
276	116	TXC140-1	ditto	30073	DB58TIS600943EH	2006-02-10		
277	117	TXC140-1	ditto	30074	DB58TIS600946EH	2006-02-11		
278	118	TXC140-1	ditto	30076	DB58TIS601002EH	2006-02-11		
279	119	TXC140-1	ditto	30075	DB58TIS601005EH	2006-02-11		
280	120	TXC140-1	ditto	30077	DB58TIS601006EH	2006-02-13		
281	121	TXC140-1	ditto	30082	DB58TIS601586EH	2006-03-16		
282	122	TXC140-1	ditto	30084	DB58TIS601590EH	2006-03-16		
283	123	TXC140-1	ditto	30081	DB58TIS601702EH	2006-03-15		
284	124	TXC140-1	ditto	30080	DB58TIS601874EH	2006-03-15		
285	125	TXC140-1	ditto	30079	DB58TIS601908EH	2006-03-15		
286	126	TXC140-1	ditto	30083	DB58TIS601993EH	2006-03-16		
287	127	TXC140-1	ditto	30078	DB58TIS601995EH	2006-03-15		
288	128	TXC140-1	ditto	30085	DB58TIS602592EH	2006-03-29		
289	129	TXC140-1	ditto	30087	DB58TIS602593EH	2006-03-30		
290	130	TXC140-1	ditto	30088	DB58TIS602594EH	2006-03-30		
291	131	TXC140-1	ditto	30089	DB58TIS602594EH	2006-06-07		
292	132	TXC140-1	ditto	30090	DB58TIS602594EH	2006-06-07		
293	133	TXC140-1	ditto	30091	DB58TIS602594EH	2006-06-07		
294	134	TXC140-1	ditto	30086	DB58TIS602595EH	2006-03-29		
295	135	TXC140-1	ditto	30092	DB58TIS604970EH	2006-06-08		
296	136	TXC140-1	ditto	30093	DB58TIS605356EH	2006-06-15		
297	137	TXC140-1	ditto	30096	DB58TIS605357EH	2006-06-17		
298	138	TXC140-1	ditto	30097	DB58TIS607	2006-06-16		
299	139	TXC140-1	ditto	30095	DB58TIS605358EH	2006-06-17		
300	140	TXC140-1	ditto	30094	DB58TIS605359EH	2006-06-15		
301	141	TXC140-1	ditto	30100	DB58TIS606511EH	2006-07-13		
302	142	TXC140-1	ditto	30098	DB58TIS606512EH	2006-07-10		
303	143	TXC140-1	ditto	30099	DB58TIS606514EH	2006-07-11		
304	1	S14L5C	ditto	DHKHEBC0E70001967	DB58TIS700135EH	2007-01-08	2007-01-24	2007-03-16
305	2	S14L5C	ditto	DHKHEBC0L70001968	DB58TIS700136EH	2007-01-10	2007-01-24	2007-03-16
306	3	S14L5B	ditto	DHKHEBC0S70001969	DB58TIS700137EH	2007-01-10	2007-01-24	2007-03-20
307	4	S14L5C	ditto	DHKHEBC0L70001971	DB58TIS700294EH	2007-01-11	2007-01-24	2007-03-19
308	5	S14L5B	ditto	DHKHEBC0P70001982	DB58TIS702111EH	2007-03-02	2007-03-30	2007-04-27
309	6	S14L5B	ditto	DHKHEBC0C70001983	DB58TIS702113EH	2007-03-02	2007-03-30	2007-04-26
310	7	S14L5D	ditto	DHKHEBC0S70001981	DB58TIS702115EH	2007-03-02	2007-06-30	2007-07-30
311	8	S14L5B	ditto	DHKHEBC0T70001993	DB58TIS705009EH	2007-07-12	2007-07-23	2007-09-12
312	9	S14L5B	ditto	DHKHEBC0A70001992	DB58TIS706700EH	2007-07-03	2007-07-20	2007-08-22
313	10	S14L5B	ditto	DHKHEBC0H70001991	DB58TIS706701EH	2007-07-03	2007-07-20	2007-08-23
314	11	S14L5B	ditto	DHKHEBC0K70001990	DB58TIS706702EH	2007-07-03	2007-07-20	2007-08-28
315	12	S14L5D	ditto	DHKHEBC0P70002002	DB58TIS707409EH	2007-08-16	2007-10-10	2007-10-29
316	13	S14L5D	ditto	DHKHEBC0C70002003	DB58TIS707603EH	2007-08-17	2007-10-10	2007-10-26
317	14	S14L5D	ditto	DHKHEBC0L70002005	DB58TIS708236EH	2007-09-05	2007-09-26	2007-11-02
318	15	S14L5D	ditto	DHKHEBC0A70002009	DB58TIS708237EH	2007-09-05	2007-09-26	2007-10-09
319	16	S14L5D	ditto	DHKHEBC0H70002008	DB58TIS708238EH	2007-09-05	2007-09-26	2007-10-09
320	17	S14L5D	ditto	DHKHEBC0K70002007	DB58TIS708256EH	2007-09-05	2007-09-26	2007-11-01
321	18	TXC140-1	ditto	30101	DB58TIS701287EH	2007-02-07		
322	19	TXC140-1	ditto	30102	DB58TIS701288EH	2007-02-07		