

INCIDENT REPORT

1) Time Incident discovered: Approximately 2:28 AM Date: 17 March 2008

2)Time Contained: Approximately 2:45 AM Date: 17 March 2008

3) Approximate location and type of accident (Fire, Spill, Explosion):

Small fire in building #1619. Started and contained in a non production outer bay on the southwest end of the building. Note: There is no electrical power nor any other known ignition source in that area. AREA USED FOR STORAGE OF CONTAINMATED MATERIALS.

4) Material Spilled/Property Damage:

None! The damage was contained to the corner's of two wooden pallets (partially burned). There were two 1 gallon size rubber buckets that were possibly contaminated with explosive residue burned on one of the pallets. Buckets were contaminated with explosive residue burned on one of the pallets. Buckets were contaminated and pallets. Smake 1500T - FIRE NOT HOT enough to burned damage to record facility on the contamination.

5) What damage to people, facility, or the environment is likely:
None.

6) How was incident discovered:

Discovery of the fire was by an employee visibly seeing smoke in the building.

7) Were procedures followed:

Yes, emergency and evacuation procedures were followed.

6) Investigation Results:

Known Facts

- a) There was no likely or known ignition source in or near the area of the fire.
- b) The fire started in an isolated area.
- c) No known personnel were in that area.
- d) Fire contained and extinguished with an ABC fire extinguisher.

Unknown Facts

- a) Fire ignition source.
- b) Extent of contamination on pallets and rubber buckets.

7) Investigation Conclusions:

Inconclusive evidence to determine the actual cause of this fire. This investigation will continue.

- 8) What has been done to prevent a reoccurrence? Describe any corrective actions:
 - a) Continuous training in Housekeeping Procedures.
 - b) Reinforcement of Non Smoking Policy.

Investigated by:

Print name: Kenneth Lampkin

Signature: Signature: Wanager
Title: Quality/Safety Manager

Phone # (318) 382-8700 Date: 02 April 2008

They believe FIRE WAS STARTED BY AND Employee Smoking AND TOSSING CIGARETTE Although NO CUIDENCE OF that WAS FOUND.





