

June 21, 2018 Project No. 30401358

Ms. Maureen Hatfield

Texas Commission on Environmental Quality MC-127 VCP-CA Section, Team 1, Remediation Division P.O. Box 13087 Austin, Texas 78711-3087

RE: MONTHLY STATUS UPDATE – SOIL CAP AND CONCRETE CAP REPAIRS
UNION PACIFIC RAILROAD HOUSTON WOOD PRESERVING WORKS FACILITY
4910 LIBERTY ROAD FACILITY, HOUSTON, TEXAS
POST-CLOSURE CARE PERMIT NO. HW-50343; INDUSTRIAL SWR NO. 31547

Dear Ms. Hatfield:

Golder Associates, Inc. (Golder), formerly Pastor, Behling & Wheeler, LLC (PBW), on behalf of Union Pacific Railroad Company, is pleased to provide this monthly status update for the implementation of the cap repairs identified in the Updated Post-Response Action Care Report (PRACR) dated January 16, 2018 for the UPRR Houston Wood Preserving Works Facility (the Site). Monthly status updates were requested by the Texas Commission on Environmental Quality (TCEQ) in a letter dated March 20, 2018.

A brief description of the need repairs discussed in the Updated PRACR and the current status of the repairs is provided below:

- Soil Cap Repairs to the soil cap were conducted on June 12 and 13, 2018. The repairs included filling in with topsoil and re-seeding minor erosion rills and revegetating a few bare spots along the slopes of the soil cap. Erosion mats were placed in areas where larger repairs were made. A photographic log of the soil cap repairs is provided in Attachment A.
- Concrete Cap (Englewood Intermodal Yard) Repairs to the concrete cap include addressing the seep area within parking slots B100 to B109 where a tar-like substance was observed surfacing through the joints and cracks in the concrete and asphalt surfaces. Golder continues to conduct weekly inspections of the affected area. When significant amounts of the tar-like substance surfaces, a remediation contractor (United States Environmental Services (USES)) is notified to mobilize to the Site to remove and properly dispose of the material. Golder has finalized a response action design to address future surfacing of the tar-like substance. We plan to submit request for bids from potential

Golder Associates Inc.

2201 Double Creek Dr, Suite 4004, Round Rock, Texas, USA 78664

T: +1 512 671-3434 F: +1 512 671-3446

Texas Commission on Environmental Quality

Ms. Maureen Hatfield Project No. 30401358

June 21, 2018

contractors by the end of June to implement the design. Depending on the selected contractor's schedule, the concrete cap repairs will likely be conducted in July 2018 or August depending on contractor's schedule.

Once the repairs to the concrete cap have been completed, UPRR will submit an Updated PRACR summarizing the repairs to both caps.

If you have any questions or need additional information, please feel free to call me at (512) 671-3434 or Mr. Kevin Peterburs of UPRR at (414) 267-4164.

Sincerely,

Golder Associates Inc.

Eric C. Matzner, P.G.

Senior Consultant / Associate

ECM

CC: Mr. Kevin Peterburs, UPRR - Milwaukee, WI

Attachments: Attachment A - Photographic Log

j:\1358 - uprr houston preserving works\pracr\tceq comment letter\houston, tx - wood preserving works - swr 31547 - monthly status update - cap repairs 20180621.docx



2

ATTACHMENT A

Soil Cap Repair Photographic Log



PHOTOGRAPHIC LOG

Client Name:

Union Pacific Railroad

Site Location:

Houston Wood Preserving Works, 4910 Liberty Road, Houston, Texas

Project No. 1358-603

Photo No.

Date: 06/12/18

Description:

Soil Cap Area:

Repairs to the soil cap facing southwest, after placement of topsoil and erosion mats.

Lat: 29.78783208, Long: -95.31881189



Photo No.

to No. Date: 06/12/18

Description:

Soil Cap Area:

Soil cap, facing northeast, view of repaired area, topsoil and erosion mat.

Lat: 29.78783208, Long: -95.31881189





PHOTOGRAPHIC LOG

Client Name:

Union Pacific Railroad

Site Location:

Houston Wood Preserving Works, 4910 Liberty Road, Houston, Texas

Project No. 1358-603

Photo No.

Date: 06/13/18

Description:

Soil Cap Area:

Soil cap, facing east, view of repaired area, topsoil and erosion mat, Liberty Rd to the left, soil cap area to the right.

Lat: 29.78829978, Long: -95.31786008



Photo No.

Date: 06/13/18

Description:

Soil Cap Area:

Repairs to soil cap, facing west, view of area being repaired, placing topsoil and erosion mat, Liberty Rd to the right.

Lat: 29.78752364, Long: -95.31833703





PHOTOGRAPHIC LOG

Client Name:

Union Pacific Railroad

Site Location:

Houston Wood Preserving Works, 4910 Liberty Road, Houston, Texas

Project No. 1358-603

Photo No. 5

Date: 06/13/18

Description:

Soil Cap Area: Repairs to the west side of the soil cap facing north, after placement of topsoil.

Lat: 29.78597686, Long: -95.32099756



Photo No. 6

Date: 06/13/18

Description:

Soil Cap Area:

Placement of topsoil in areas of settlement along the concrete barriers, facing eastsoutheast.

Lat: 29.78695886, Long: -95.31757222

