FIGURE 2

PCE PLUME (µg/L) IN THE ALLUVIAL
AQUIFIER AT THE MAINTENANCE SHOP AREA
1ST QUARTER/MARCH 2001



e:\005\264.dgn 06/14/01 04:24:05 PM