U.S. Environmental Protection Agency (EPA)

Clean Air Status and Trends Network (CASTNet)

Quality Assurance Project Plan

Index to Appendices 1 through 9

December 2002

Prepared by:

Harding ESE

A MACTEC Company

Index to the Quality Assurance Project Plan

Appendices 1 through 9

Appendix 1:	Harding ESE Field Standard Operating Procedures
I.	**Site Selection Procedures**
A.	Site Installation, Initiation, and Operator Training
B.	Measurement of Leaf Area Index
II.	**Site Operations**
A.	Site Operator Checklist
B.	Site Operator Instructions with R.M. Young Equipment
C.	Site Operator Instructions with Climatronics Equipment
D.	Field Operations Manual
1	Odessa Data Acquisition System
2	Filter Sampling
3	Ozone Monitoring
4	Tipping Bucket Rain Gauge
5	Wetness Sensor
6	Climatronics Meteorological System
7	R.M. Young Meteorological System
III.	**Field Calibrations**
A.	Field Calibrations Manual
B.	Procedures for Modification of the Site Ozone Analyzer
IV.	**Certification Laboratory**
A.	Primary Standards
1	Ozone
2	BIOS Flow Meter
3	Eppley Pyranometer
4	Thermometers
5	Vaportron H-100L Precision Relative Humidity Lab
6	Fluke Multimeter 8060A
7	Relative Humidity Saturated Aqueous Salt Solutions
B.	Transfer Standards
1	Calibration Equipment and Spare Parts Box
2	Datel Voltage Source (350A)
3	Ozone Analyzer
4	BIOS DryCal Primary Air Flow Meter
5	Transfer RTD Eutechnics, Transfer RTD HY-CAL and Platinum RTD
6	R.M. Young Synchronous Motor Model 18802
7	Brunton Pocket Transit
8	Rotronics GTL Hygrometer Model A1
9	R.M. Young Solar Radiation Transfer System
10	Relative Humidity Saturated Aqueous Salt Solution
C.	Site Instrumentation
1	Field Equipment Sign-In and Sign-Out
2	TECO Ozone Monitors, Models 49C and 49-103
3	Mass Flow Controller
4	Wetness Sensor
5	Tipping Bucket Rain Gauge

Appendix 1:	**Harding ESE Field Standard Operating Procedures (con't)**
C.	Site Instrumentation (continued)
6	Climatronics
a	Wind Direction
b	Wind Speed
c	Temperature/Delta Temperature
d	Relative Humidity
e	Solar Radiation
7	R.M. Young
a	Wind Direction
b	Wind Speed
c	Temperature/Delta Temperature
d	Relative Humidity - Rotronics
e	Solar Radiation
Appendix 2:	**Site Contact List**
	Site Contact List
Appendix 3:	**Air Resource Specialists Standard Operating Procedures**
I.	**NPS AIR MONITORING NETWORK FIELD OPERATOR PROCEDURES**
3176	Station Operator Maintenance Procedures for Meteorological Monitoring Sites Using the DataView System
3176-3100	Checklist Instruction – Weekly Station Visit – Wind Speed/Wind Direction Sensor (Climatronics)
3176-3101	Checklist Instruction – Weekly Station Visit – Wind Speed/Wind Direction Sensor (R.M. Young)
3176-3105	Checklist Instruction – Weekly Station Visit – Temperature Sensor (Climatronics)
3176-3107	Checklist Instruction – Weekly Station Visit – Relative Humidity (Climatronics)
3176-3110	Checklist Instruction – Weekly Station Visit – Temperature/ Delta Temperature Sensor (Climatronics)
3176-3111	Checklist Instruction – Weekly Station Visit – Temperature/Delta Temperature Sensor (R.M. Young)
3176-3115	Checklist Instruction – Weekly Station Visit – Air Temperature and Relative Humidity Sensor (Rotronics)
3176-3120	Checklist Instruction – Weekly Station Visit – Relative Humidity Sensor (Rotronics)
3176-3130	Checklist Instruction – Weekly Station Visit – Solar Radiation Sensor (Climatronics)
3176-3131	Checklist Instruction – Weekly Station Visit – Solar Radiation Sensor (R.M. Young)
3176-3140	Checklist Instruction – Weekly Station Visit – Wetness Sensor (R.M. Young)
3176-3150	Checklist Instruction – Weekly Station Visit – Precipitation Sensor (Climatronics)
3178	Station Operator Maintenance Procedures for Gaseous Monitoring Sites Using the DataView System
3178-3101	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (Monitor Labs ML8810) Ozone Calibrator (Dasibi 1003-PC) CASTNet Dry Deposition
3178-3102	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (Monitor Labs ML8810) Ozone Calibrator (Dasibi 1008-PC)
3178-3105	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (Dasibi 1003-AH) (Ozone Calibrator (Dasibi 1003-PC)

Appendix 3:	Air Resource Specialists Standard Operating Procedures (con't)
I.	**NPS AIR MONITORING NETWORK FIELD OPERATOR PROCEDURES**
3178-3106	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (Dasibi 1003-AH) Ozone Calibrator (Dasibi 1003-PC) CASTNet Dry Deposition
3178-3110	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (TEI 49) Ozone Calibrator (Dasibi 1003-PC) CASTNet Dry Deposition
3178-3111	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (TEI 49) Ozone Calibrator (Dasibi 1003-PC)
3178-3113	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (TEI 49) Ozone Calibrator (TEI 49) CASTNet Dry Deposition
3178-3115	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (TEI 49C) Ozone Calibrator (TEI 49C)
3178-3116	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (TEI 49C) Ozone Calibrator (TEI 49C) CASTNet Dry Deposition
3178-3117	Checklist Instruction – Weekly Station Visit – Sulfur Dioxide Analyzer (TEI 43C TL) Gas Dilution Calibrator (TEI 146)
3178-3121	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (API 400) Ozone Calibrator (Dasibi 1003-PC) CASTNet Dry Deposition
3178-3122	Checklist Instruction – Weekly Station Visit – Ozone Analyzer (API 400) Ozone Calibrator (Dasibi 1003-PC)
3178-3126	Check Checklist Instruction – Weekly Station Visit – Ozone Analyzer (CSI OA 325-2) Ozone Calibrator (Dasibi 1003-PC) CASTNet Dry Deposition
3178-3300	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (ML 8810) Ozone Calibrator (Dasibi 1003-PC)
3178-3303	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (ML 8810) Ozone Calibrator (Dasibi 1008-PC)
3178-3305	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (Dasibi 1003-AH) Ozone Calibrator (Dasibi 1003-PC)
3178-3310	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (TEI 49) Ozone Calibrator (Dasibi 1003-PC)
3178-3312	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (TEI 49) Ozone Calibrator (TEI 49)
3178-3315	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (TEI 49C) Ozone Calibrator (TEI 49C)
3178-3317	Checklist Instruction – Multipoint Calibration – Sulfur Dioxide Analyzer (TEI 43C-TL) Dynamic Gas Calibrator (TEI 146) (Not Included)
3178-3320	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (API 400) Ozone Calibrator (Dasibi 1003-PC)
3178-3325	Checklist Instruction – Multipoint Calibration – Ozone Analyzer (CSI OA 325-2) Ozone Calibrator (Dasibi 1003-PC)
3178-3350	Checklist Instruction – Weekly Station Visit – Sulfur Dioxide Analyzer (TEI 43C) Dynamic Gas Calibrator (TEI 146C)
3178-3352	Checklist Instruction – Weekly Station Visit – Sulfur Dioxide Analyzer (TEI 43C) (70 ppb – 90 ppb) Dynamic Gas Calibrator (TEI 146)
3178-3354	Checklist Instruction – Weekly Station Visit – Sulfur Dioxide Analyzer (TEI 43C) (360 ppb – 440 ppb) Dynamic Gas Calibrator (TEI 146)
3178-3356	Checklist Instruction – Weekly Station Visit – Sulfur Dioxide Analyzer (TEI 43C) (760 ppb – 840 ppb) Dynamic Gas Calibrator (TEI 146)

Appendix 3:	Air Resource Specialists Standard Operating Procedures (con't)
II	**INFORMATION MANAGEMENT CENTER (IMC) PROCEDURES**
3340	Information Management Center (IMC) Concept and Configuration
3345	Day to Day Network Operations Technical Support for the National Park Service Gaseous and Meteorological Monitoring Program
3350	Collection of Ambient Air Quality and Meteorological Monitoring Data and Site Documentation
3350-4000	Collection of Ambient Air Quality and Meteorological Monitoring Data Via Telephone Modem
3350-4005	Collection of DataView Files via Telephone Modem
3450	Ambient Air Quality and Meteorological Monitoring Data Validation
3450-5000	Ambient Air Quality and Meteorological Monitoring Data – Level 0 Validation
3450-5010	Ambient Air Quality and Meteorological Monitoring Data –Preliminary Validation
3450-5020	Ambient Air Quality and Meteorological Monitoring Data – Final Validation
3550	Ambient Air Quality and Meteorological Monitoring Data Reporting
3550-5000	Ambient Air Quality and Meteorological Monitoring Data –Monthly Reporting
3550-5100	Ambient Air Quality and Meteorological Monitoring Data – Annual Reporting
3550-5200	Handling Requests for Ambient Air Quality and Meteorological Monitoring Data
3550-5300	Submitting Ambient Air Quality and Meteorological Monitoring Data to the EPA AIRS Database
3650	IMC Manager's Maintenance Responsibilities for the Ambient Air Quality Database Management System (AQDBMS)
	Air Quality Database Management System (AQDBMS) User's Guide
	Air Quality Database Management System (AQDBMS) Database Administrator and Programmer's Reference
	Air Quality Database Management System (AQDBMS) EPA AIRS Reference
	Stackplot Program User's Guide
III.	**FIELD MAINTENANCE AND CALIBRATION PROCEDURES**
3000	Procedures for Semiannual Maintenance Visits to a National Park Service Ambient Air Monitoring Station
3100	Calibration of Ambient Air Quality Analyzers
3100-2000	Calibration and Routine Maintenance of Monitor Labs (ML) 8810 Ozone Analyzers
3100-2001	Calibration and Routine Maintenance of Dasibi 1003-AH, 1003 RS or 1003-PC Ozone Analyzers
3100-2002	Calibration and Routine Maintenance of Thermo Environmental Instruments Model 49 (TECO 49) Ozone Analyzers
3100-2003	Calibration and Routine Maintenance of API Model 400 Series Ozone Analyzers
3100-2021	Calibration and Routine Maintenance of Thermo Environmental (TECO) 43C SO_2 Analyzers
3150	Calibration and Routine Maintenance of Meteorological Monitoring Systems
3150-2020	Calibration and Routine Maintenance of Campbell Scientific CS105 Barometric Pressure Sensors
3150-2100	Calibration and Routine Maintenance of Climatronics F460 or Qualimetrics 12XX Wind Speed and Direction Sensor Systems
3150-2102	Calibration and Routine Maintenance of Climatronics F460 Wind Speed and Wind Direction Sensors Used with a Campbell Scientific 21XL or CR23X Datalogger
3150-2103	Calibration and Routine Maintenance of R.M. Young Model 05305 Wind Monitor-AQ Wind Speed and Direction Sensor Systems
3150-2105	Calibration and Routine Maintenance of Climatronics or Qualimetrics Temperature/Delta Temperature Systems

Appendix 3:	Air Resource Specialists Standard Operating Procedures (con't)
III.	**FIELD MAINTENANCE AND CALIBRATION PROCEDURES**
3150-2110	Calibration and Routine Maintenance of Climatronics or Qualimetrics Dew Point/Relative Humidity Systems
3150-2113	Calibration and Routine Maintenance of R.M. Young Temperature/Delta Temperature Systems
3150-2114	Laboratory Calibration and Repair of Rotronics MP-101A AT/RH Sensors or Rotronics MP-601A Relative Humidity Sensors
3150-2115	Field Calibration and Routine Maintenance of Rotronics MP-101A AT/RH Sensors or Rotronics MP-601A Relative Humidity Sensors
3300	Certification of Ozone Transfer Standards
	CASTNet AUDIT PROCEDURES
3755	CASTNet Ambient Air Quality Monitoring Audit Procedures
3755-6100	Ozone Analyzer Audit Procedures (CASTNet Installations)
3755-6110	Meteorological Sensor Audit Procedures (CASTNet Installations)
3755-6120	Data Acquisition System Audit Procedures (CASTNet Installations)
3755-6130	Dry Deposition/Visibility Mass Flow Controlled Audit Procedures (CASTNet Installations)
3755-6140	Field Systems Audit Procedures (CASTNet Installations)
	NEPHELOMETERS
4100-3150	Routine Site Operator Maintenance Procedures for OPTEC NGN-2 Nephelometer Systems (CASTNet Installations)
4100-3350	NGN-2 Nephelometer Monitoring System Diagrams and Component Descriptions
4100-3375	Replacing and Shipping Nephelometer System Components
4100-3400	Nephelometer Annual Laboratory Maintenance (IMPROVE Protocol)
4200-2000	Calibration of Optec NGN-2 Nephelometers (IMPROVE Protocol)
4400-5010	Nephelometer Data Reduction and Validation (IMPROVE Protocol)
4500-5000	Nephelometer Data Reporting (IMPROVE Protocol)
4600-5000	Nephelometer Data Archives (IMPROVE Protocol)
Appendix 4:	Harding ESE Laboratory Standard Operating Procedures
	Laboratory - Instrumentation
GLM3180-001	Determination of Selected Inorganic Anions in Water and Air Filters by Ion Chromatography for Acid Deposition Projects (EPA Method 300.0)
GLM3180-004	Ammonia for Dry and Wet Deposition (Modified EPA Method 350.1)
GLM3180-005	Inductively Coupled Plasma Atomic Emission Spectrometry: Perkin-Elmer Optima 3000 DV (Modified EPA Method 6010B)
GLM3180-007	Hydrogen Ion (pH) in Water (EPA Method 150.1)
GLM3180-008	Specific Conductance for Wet Deposition Samples (EPA Method 120.1)
GLM3180-010	Acidity for Wet Deposition Samples (EPA Method 305.2)
GLO3180-001	Sample Container Preparation for Dry and Wet Deposition
GLO3180-002	Washing of Filter Pack Equipment, Denuders, and Filter Tweezers
GLO3180-003	Central Sample Storage Organization for Dry and Wet Deposition Samples
GLO3180-004	Filtering Wet Deposition Samples
GLO3180-005	Wet Deposition Bucket Blank Sample
GLO3180-006	Wet Deposition Field Bottle Blank Sample Preparation
GLO3180-007	Procedure for Receiving, Assigning Sample Numbers, and Shipping CASTNet Wet Deposition Sampling Kits
GLO3180-008	Receiving, Unpacking, and Login of One-Stage Filter Packs and Denuders

Appendix 4:	**Harding ESE Laboratory Standard Operating Procedures (con't)**
GLO3180-009	Preparing and Shipping the One-Stage Filter Packs and Denuders
GLO3180-010	Whatman Paper Filter Preparation with Potassium Carbonate
GLO3180-011	Coating of Ambient Air Denuder Tubes
GLO3180-012	CASTNet Three-Stage Ambient Air Filter Pack Receipt, Disassembly and Login
GLO3180-013	Preparing and Shipping the CASTNet Three-Stage Filter Packs
	Laboratory - Management
GLO3180-014	Finalization/Definalization of Data Batches
GLO3180-015	Procedure for Sample Information Changes and Additions
GLO3180-016	Procedure for Data Entry Error Correction
GLO3180-017	Computer Sample Login and Sample Arrival Notification
GLO3180-018	Available Numbers Distribution
GLO3180-019	Laboratory Information Management System (LIMS) Enterprise Backup System
GLO3180-020	Procedure for Generating the Atmospheric Concentration Reports
GLO3180-021	Data Submittal for Wet and Dry Deposition Samples
GLO3180-022	Deionized Water Quality
GLO3180-023	Setting Up Chemical Laboratory Analysis and Scheduling System (CLASS™) Field Groups and Preparing Sample Kit Labels
Appendix 5:	**Sunset Laboratory and Chester LabNet Standard Operating Procedures**
	Chester LabNet Standard Operating Procedures
AD-007.02	Laboratory Information Management System (LIMS)
AD-008.01	Sample Receipt and Log-In
AD-008.01	Sample Receipt Checklist
GR-007.02	Inspection and Preparation of Teflon Filter Media (25 mm, 37 mm, 47 mm)
GR-014.01	Gross Weighing of Teflon Filter Media (25 mm, 37 mm, 47 mm)
GR-016.01	Preparation and Use of Control Charts for Gravimetric Analysis
QA-002.02	Laboratory Data Validation
QA-008.01	Review of Data Reports
XR-002.01	Elemental Analysis of Air Filters by X-Ray Fluorescence
	Sunset Laboratory Standard Operating Procedure
	Analysis of Organic and Elemental Carbon (OC/EC) on Quartz Fiber Filters
Appendix 6:	**Harding ESE Health and Safety Plan (HASP)**
	Harding ESE Health and Safety Plan (HASP)
Appendix 6:	**Harding ESE Government Property Control Standard Operating Procedures**
	Harding ESE Government Property Control Standard Operating Procedures
Appendix 7:	**Data Operations Standard Operating Procedures**
1	Software Management Plan
2	Hardware Maintenance Plan
3	CASTNet Data Management System Application User Manual (pending)
4	Database Backups

Appendix 7:	Data Operations Standard Operating Procedures (con't)
5	Multi-Layer Model Operations
6	Data Deliverables
7	Data Analysis and Reports (pending)
Appendix 8:	Data Quality Objectives (pending)
Appendix 9:	Quality Management Plan
	MACTEC, Inc. Quality Assurance Manual Policy Volume
1.0	Organization
2.0	Quality Assurance Program
3.0	Design Control
4.0	Procurement Document Control
5.0	Instructions, Procedures and Drawings
6.0	Document Control
7.0	Control of Purchased Items
8.0	Identification and Control of Materials, Parts, and Components
9.0	Control of Special Processes
10.0	Inspection, Examination, Surveillance, and Testing
11.0	Test Control
12.0	Control of Measuring and Test Equipment
13.0	Handling, Storage, and Shipping
14.0	Inspection, Test and Operating Status
15.0	Nonconforming Materials, Parts, or Components
16.0	Corrective Action
17.0	Quality Assurance Records
18.0	Audits
	MACTEC, Inc. Quality Assurance Manual Procedure Volume
1.0	Organization
2.0	Quality Assurance Program
3.0	Design Control
4.0	Procurement Document Control
5.0	Instructions, Procedures and Drawings
6.0	Document Control
7.0	Control of Purchased Items
8.0	Identification and Control of Materials, Parts, and Components
9.0	Control of Special Processes
10.0	Inspection, Examination, Surveillance, and Testing
11.0	Test Control
12.0	Control of Measuring and Test Equipment
13.0	Handling, Storage, and Shipping
14.0	Inspection, Test and Operating Status
15.0	Nonconforming Materials, Parts, or Components
16.0	Corrective Action
17.0	Quality Assurance Records
18.0	Audits
	Checklist for Reviewing EPA Quality Management Plans