

FIGURE 2-9
9 LEVEL INFRASTRUCTURE

BUNKER HILL MINE WATER RI/FS REPORT
152215.FS.01

CH2MHILL

148562.02.01

FILE NAME: 10CXX101.DLV 10-JAN-2001