

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Reading, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA71-01_2008	Aberjona River	Boston Harbor:	5			1.7	9.2	Cause Unknown Metals Nutrients Organic enrichment/Low DO Other habitat alterations* Pathogens Unionized Ammonia	
MA92-06_2008	Ipswich River	Ipswich	5			2.0	20.4	Flow alteration* Metals Nutrients Organic enrichment/Low DO	
MA92-07_2008	Bear Meadow Brook	Ipswich	3			2.7	2.8		

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries