

January 2011 Update

Hill Air Force Base Superfund Site

Davis and Weber Counties, Utah
(Review Date 12/31/2008)

Highlights since the 2008 Five-Year Review

- ESD OU2 eliminated pre-treatment (steam stripper) November 2009
- Operable Unit (OU) 10 Feasibility Study completed September 2009
- OU9 Feasibility Study completed September 2010
- Remedial Action Completion Report OU2 December 2010

Issues & Recommendations Update

Issues	Recommendations/ Follow-up	Follow-up Actions (Status/Due Date) January 2011	Resp. Party
1) Toxicity factors and cleanup standards are likely to change, prior to achievement of site closure.	Continue to assess site risks and exposure pathways in response to revised toxicity factors and clean-up standards. Complete for this five year review. Remedy modifications are not recommended as the ICs are protective; if exposure pathways become complete, risk and clean-up goals will be reevaluated.	Complete	Air Force

Issues	Recommendations/ Follow-up	Follow-up Actions (Status/Due Date) January 2011	Resp. Party
<p>2) Periodic, integrated reviews of O&M and LTM data to support remedy performance and protectiveness tracking have not been documented outside of the PSV report process.</p>	<p>Perform periodic, integrated reviews of O&M and LTM data to support remedy performance and protectiveness tracking and document results. Integrated reviews of O&M data are reported annually in cost and performance reports, and LTM data are reported in quarterly and annual reports. Remedy performance is evaluated rigorously through the performance sampling verification report.</p>	<p>Complete</p>	<p>Air Force</p>
<p>3) The IAP is currently managed as a separate program but covers multiple OUs.</p>	<p>Create a separate OU for management of the Indoor Air Program (IAP). Hill AFB is no longer considering creating an OU for the IAP to manage offsite residential indoor air issues.</p>	<p>Considered not implemented 11/22/10</p>	<p>Air Force</p>
<p>4) The deferred sites have been returned to site inspection status, and have not yet been investigated.</p>	<p>Investigation of the deferred sites should proceed. Based on results of the investigation described in the 2008 work plan only one (Building 2214) of the deferred sites will be remediated. NFRAP for the other sites.</p>	<p>Complete 12/09/10</p>	<p>Air Force</p>