## **Executive Summary**

ID No. SWR No. 31547

Page 1 of 4

Report Date:
08/20/20 – Rev 2

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY Response Action Completion Report

## **Cover Page**

check one: Initial RACR submittal for this on-site property Report date: TCEQ Region No.:	number, etc) SWR No X Subsequent R	
	uperfund PRP Lead (Ma Iunicipal Solid Waste Pel	
On-Site Property Information On-Site Property Name: Union Pacific Railroad Houston Wood Pre	serving Works Site	
Street no. 4910 Pre dir: Street name Liberty	Street type: Road I	Post dir:
City: Houston County: Harris	County Code: 101	Zip: 77007
	south of Liberty Rd. betwood St, and north of Lee	
Latitude: Decimal Degrees (circle one) North Longitude: Decimal Degrees (circle one) West  95.321062		
Off-Site Affected Property Information Off-Site Affected Property Name:		
Street no Pre dir: Street name:		Post dir:
City: County:	County Code:	
Check if there are no off-site properties affected		
Contact Person Information and Acknowledgement Person (or company) Name: Union Pacific Railroad		
Contact Person Information and Acknowledgement	Title: Manager, Sit	Remediation
Contact Person Information and Acknowledgement Person (or company) Name: Union Pacific Railroad Contact Person: Kevin Peterburs	Title: Manager, Sit	e Remediation
Contact Person Information and Acknowledgement Person (or company) Name: Union Pacific Railroad Contact Person: Kevin Peterburs  Mailing Address: 4823 N 119 <sup>th</sup> Street		
Contact Person Information and Acknowledgement Person (or company) Name: Union Pacific Railroad Contact Person: Kevin Peterburs  Mailing Address: 4823 N 119 <sup>th</sup> Street	E-mail address	e Remediation  kipeterb@UP.COM

## **Executive Summary**

ID No. SWR No. 31547

Report Date: 08/20/20 - Rev 2

Page 2 of 4

Check the rep	orts/forms su	ubmitted:						
	ementation N	Notice Sub n - Approval (	omittal date: date:					
Remedy Star			<del></del>					
-		n - Approval (	date: the TCEQ A	nder review. Con Area of Contamin 2015 (and amen	nation (AOC)	Appro	val dat	
contains a PC decontaminati media with a F	LE zone and on, physical PCLE zone w	I specify the control, or in vas not addre	soil, groundwater, response action ta estitutional control a essed in the respo	ken for each me action that was u nse action, provi	dia. Indicate t sed in the res de an explana	he type ponse ition be	e of ren action. elow.	noval, . If a
Media	COCs <sup>1</sup>	Removal	Decontamination	Physical Control	Institutional Control	Modified Response Objective <sup>2</sup>		
						PMZ	WCU	TI
Surface Soil	Benzene, SVOCs, metals	Х		Х	Х			
Subsurface Soil	SVOCs			Х	Х			
action?			zone that was no		•	_	<b>X</b> ye	es no
			essing the PCLE zo			C 41		1
•		•	port (RACR) only ponse action for the		•			
			ovember 21, 2014	•				
_		*	nd August 31, 202				-	
· ·			esponse action, a s	0 11		•	•	-
the groundwa			1 /	1				
			ted property: ite property (if kno	_ Residential wn): Resi	X Comme			
Explain why ve	ou believe th	e response a	action to be compl	ete.				
					AOs) for surf	ace an	d subsi	urface
As discussed in the RAP (PBW, 2015), the response action objectives (RAOs) for surface and subsurface soil PCLE Zones was to excavate impacted soils with COCs above cPCLs and consolidate the soils within								
		_	ion approach, and					
using physica	al barriers su	ch that on-si	te commercial/ind	ustrial and off-sit	te residential 1	pathwa	ys will	not be

Specify either a specific COC or, if the response action is the same for all COCs in one type, specify the type of COC (for example, VOCs, SVOCs, metals).
 If a modified groundwater response objective was used, check the type(s) of modifications.

### **Executive Summary**

ID No. SWR No. 31547 Repo

Report Date: 08/20/20 - Rev 2

Page 4 of 4

excavation of the top 9-inches (consolidated within the on-site soil-capped area) and construction of a physical barrier (concrete sidewalk) preventing contact with remaining surface soils and limiting infiltration. After the soils were excavated, UPRR constructed a concrete sidewalk approximately 8 feet wide and 690 feet long serving as the physical barrier covering the remaining surface soil PCLE zone within the City of Houston ROW. As part of the post-response action care detailed in the RAP (PBW, 2015), the concrete sidewalk will be inspected to ensure the physical barrier provides protection for residential receptors against exposure to the COCs above cPCLs in surface soils in this area.

- Englewood Intermodal Yard area: The surface soil PCLE zone in the Intermodal Yard area is currently covered with a physical barrier (concrete pavement), preventing contact with the soil PCLE Zone and infiltration. As part of the post-response action care, the concrete pavement in the area of the surface soil PCLE Zone will be inspected to ensure continued on-site worker protection.
- <u>UPRR Main Lines Ballast Area:</u> The area between the former HWPW operational areas and the Englewood Intermodal Yard (approximately 100 feet width) is covered with railroad ballast, ties, and rail. UPRR will use the existing railroad ballast as an engineering control for preventing onsite worker exposure to impacted surface soils in this area.

The physical controls at the Site will be maintained and appropriate maintenance, repair of the caps will be performed as needed. UPRR will implement a health and safety program to restrict any construction activity within the capped areas. In the event construction activities are necessary, a health and safety plan and soil management plan will be implemented to ensure worker protection and proper management of soils with COCs above cPCLs.

#### **Checklist for Report Completeness**

Page 1 of 2

ID No. SWR No. 31547 Report Date: 08/20/20

- Rev 2

#### **Checklist for Report Completeness**

Use this checklist to determine the portions of the form that must be submitted for this report. Answer all questions by checking Yes or No. If the answer is Yes include that portion of the report. If the answer is No, do not complete or submit that portion of the report. All form contents that are marked "Required" must be submitted. Form contents marked with an asterisk (\*) are not included in the blank form and are to be provided by the person.

Report Contents  $\boxtimes$ Required **Cover Page**  $\boxtimes$ Required **Executive Summary** Required **Checklist for Report**  $\boxtimes$ Completeness Worksheet 1.0 Required  $\boxtimes$ Confirmation of Response Action Objectives Attachment 1A\*  $\boxtimes$ Required Maps and Cross Sections Required Attachment 1B\* Graphs Attachment 1C\* Required Response Action Diagrams No 🗌 Was a plume management zone used as part of the Worksheet 2.0 response action? Plume Management Zone Details provided in the Response Action Plan, Revision Attachment 2A\* 5 – August 31, 2020 Map of Plume Management Zone No 🛛 Was an area of technical impracticability approved for use ☐ Yes Worksheet 3.0 as part of the response action? Technical Impracticability Attachment 3A\* Map of Technical Impracticability Area X Yes No 🗌 Were institutional controls used or required as part of the Worksheet 4.0  $\boxtimes$ Institutional Controls response action? Required Worksheet 5.0 Performance Measures and Problems No 🗌 Did the response action require any operation and Yes Worksheet 6.0 maintenance activities? Operation and Maintenance No 🛛 Has there been any change to the plans for post-response ☐ Yes Worksheet 7.0 action care from that submitted in the RAP? Post-Response Action Care No 🛛 Was any information for this report obtained from outside ☐ Yes Appendix 1\* sources? References No 🛛 Was an ESA and/or Compensatory Restoration used as Appendix 2\* Yes part of the response action? **ESA** and Compensatory Restoration Were institutional controls or landowner concurrence Appendix 3\* No 🗌 Yes required in the response action? Institutional Controls and Reserved Landowner Concurrence

# APPENDIX 3 INSTITUTIONAL CONTROLS AND LANDOWNER CONCURRENCE RESERVED