Table 1

Community Continuous Air Monitoring Results East Palestine Derailment Site East Palestine, Columbiana County, Ohio

Monitoring Period: 09/22/2023 00:00 through 09/23/2023 10:22

Air Monitoring Instrument: Serial Number	Analyte	Screening Level ¹	Screening Level Exceeded?	8-hour Period Concentration Range	Average of All 8-hour Periods
8533183117	$PM_{2.5} (mg/m^3)$	$0.035 \text{ (mg/m}^3\text{)}$	No	0.018 to 0.020	0.019
	$PM_{10} (mg/m^3)$	$0.070 \text{ (mg/m}^3\text{)}$	No	0.019 to 0.026	0.022
8533230504	$PM_{2.5} (mg/m^3)$	$0.035 \text{ (mg/m}^3\text{)}$	Yes ²	0.009 to 0.048	0.020
	$PM_{10} (mg/m^3)$	$0.070 \text{ (mg/m}^3\text{)}$	No	0.011 to 0.049	0.022
8533230702	$PM_{2.5} (mg/m^3)$	$0.035 \text{ (mg/m}^3\text{)}$	Yes ²	0.011 to 0.036	0.016
	$PM_{10} (mg/m^3)$	$0.070 \text{ (mg/m}^3\text{)}$	No	0.014 to 0.038	0.021
W01A00002133	VOC (ppm)	0.5 (ppm)	No	0.00 to 0.11	0.03
W01B00002209	VOC (ppm)	0.5 (ppm)	No	0.00 to 0.09	0.03
W01B00002220	VOC (ppm)	0.5 (ppm)	No	0.00 to 0.00	0.00

Notes:

Abbreviations:

mg/m³ - milligrams per meter cubed

PM_{2.5} - Particulate Matter, diameter 2.5 micrometers and smaller

 PM_{10} - Particulate Matter, diameter 10 micrometers and smaller

ppm - Parts per million

S/N - Serial number

VOC - Volatile organic compound

We are in the process of ensuring this document is accessible to all audiences. If you need assistance accessing this document, or any materials on the EPA East Palestine, Ohio emergency response webpages, please contact the Region 5 Public Information Officer on-call r5_eastpalestine@epa.gov

¹ Site-Specific Screening Levels stated in the Tetra Tech Air Monitoring and Sampling Plan. Screening levels were modified on March 16, 2023 to reflect updated operation procedures on when to apply mitigation methods to reduce dust. Action levels set by health departments have not changed.

² Vehicle traffic observed during monitoring period near monitoring instrument.

Air monitoring measurements have been averaged over a 8-hour time period and summarized above.

Air monitoring is not performed during inclement weather conditions/rain and thunderstorms.

