

Municipality/Organization: Town of Swampscott, Massachusetts

EPA NPDES Permit Number:

MassDEP Transmittal Number: W- 041272

Annual Report Number Year 7
& Reporting Period: April 1, 2009 – March 31, 2010

Received
4/21/10

P

**NPDES PII Small MS4 General Permit
Annual Report
(Due: May 1, 2010)**

Part I. General Information

Contact Person: Gino A. Cresta, Jr.

Title: Director of Public Works

Telephone #: 781-596-8860

Email: gcresta@town.swampscott.ma.us

Mailing Address: 22 Monument Avenue, Swampscott MA 01907

Certification:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature:



Printed Name: Andrew W. Maylor

Title: Town Administrator

Date:

April 14, 2010

Part II. Self-Assessment

The Town of Swampscott, Massachusetts has completed the required self-assessment and has determined that, based on available information, the Town is in compliance with the conditions of the permit, with the minor exception of where implementation of our minimum control measures did not meet our stated schedule documented as part of the Notice of Intent. In these instances, alternative BMPs have been performed or proposed as described below:

- **BMP 1-1:** The Town will continue to post stormwater information and place brochures in public buildings in place of having speakers in two schools per year due to staffing shortages.
- **BMP 3-4:** The Town inspected 15,000 linear feet of storm drains in 2004. 5,000 LF of underdrain and an additional 7,000 LF of storm drain were television inspected between March and October, 2008. The underdrain inspected discharges to the stormwater system within the Stacey's Brook drainage area where there is known contamination. This falls short of televising the entire storm drain system as proposed in BMP 3-4, however, we continue to move towards elimination of illicit connections.
- **BMP 6-5:** Limited staffing resources has eliminated the possibility of applying for tree survey grants through US Forestry. We are going to pursue utilizing a community service group to conduct the tree survey such as girl scouts or boy scouts.

Part III. Summary of Minimum Control Measures

1. Public Education and Outreach

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 7	Planned Activities – Permit Year 8
1. Public Education and Outreach					
1-1	Speakers	Director of Public Works	Call two schools per year	Posted stormwater posters in public buildings. Will continue through permit term.	Stormwater posters posted throughout term.
1-2	Local cable access spots	Director of Public Works	Produce two 5-minute spots	In compliance.	No activity planned.
2. Public Involvement and Participation					
2-1	Public Notification	Director of Public Works	Posting of all appropriate meetings	All DPW meetings (one per month) are posted in Town Hall.	Continue to post notices of appropriate meetings.
2-2	Household hazardous waste collection	Health Director	One collection per year	Household hazardous waste collection days were held June 6 and November 7, 2009.	Household hazardous waste collection days June 5 and November 6, 2010.
2-3	Stencil catch basins that drain to sensitive areas	Director of Public Works	Stencil fifty (50) catch basins per year	The approximate 60 catchbasins stenciled in 2005 are in good shape.	Continue to monitor the condition of the stenciled catch basins.
2-4	Seedlings for Arbor Day	Director of Public Works / Tree Warden	Ten (10) seedlings per year for two (2) years	Planted ceremonial tree on Arbor Day, 2010.	Plant on Arbor Day, 2011
3. Illicit Discharge Detection and Elimination					
3-1	Map outfalls and receiving waters	Director of Public Works	Updated map by the end of the second year	In compliance	No activity planned
3-2	Stormwater bylaw	Director of Public Works	Draft completed in time to submit to Town Meeting	Bylaw is still under review by Town Officials. Town formed a "bylaw review committee" which will also be reviewing the new bylaw.	Present for enactment in Spring, 2010 at Town Meeting.
3-3	Dry weather screening of outfalls	Director of Public Works	Two rounds of sampling in 2004	The board of Health takes samples from beach areas during the Summer	Continue to investigate sources of high bacterial counts.
3-4	Illicit discharge elimination	Director of Public Works	Televise the entire system by the end of the term	Continued inspection of all remaining storm drains is cost-prohibitive. CCTV inspection of underdrains contributing to the stormwater system helped to locate sources of contamination in 2009, with plans to remedy two point sources in Summer, 2010.	Continue to investigate illicit connections to Stacey's Brook drainage area and design further improvements to install in Fall 2010 using SRF funds already appropriated.

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 7	Planned Activities – Permit Year 8
4. Construction Site Stormwater Runoff Control					
4-1	Construction site bylaw and ordinance	Planning Board, Building Inspector, DPW, ERAC	Present draft bylaw to Town Meeting in 2004	Bylaw is still under review by Town Officials. Town formed a "bylaw review committee" which will also be reviewing the new bylaw.	Present for enactment in Spring, 2010 at Town Meeting.
4-2	Public Comment	ZBA, ConComm, Planning Board, DPW	Receive input on draft bylaw at public meetings	Received input at various public meetings.	Continue to receive input at public meetings.
4-3	Review site plans	Building Inspector, DPW, ZBA, ConComm	Add stormwater management to scope of review	In compliance, continue to review site plans for stormwater program compliance.	Continue to review site plans for stormwater program compliance.
4-4	Enforcement Procedures	Planning Board, ConComm	Notification to the boards about enforcement procedures	Enforcement procedures are still under review by Town Officials. Town formed a "bylaw review committee" which will also be reviewing the enforcement procedures.	Present for enactment in Spring, 2010 at Town Meeting.
5. Post-Construction Stormwater Management in New Development and Redevelopment					
5-1	BMP manual	DPW, ConComm	BMP manual selected	In compliance, continue to recommend BMP manual to local developers	Continue to recommend BMP manual to local developers
5-2	Runoff Controls	Director of Public Works	Draft bylaw to Town Meeting	Bylaw is still under review by Town Officials. Town formed a "bylaw review committee" which will also be reviewing the new bylaw.	Present for enactment in Spring, 2010 at Town Meeting.

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 7	Planned Activities – Permit Year 8
6. Pollution Prevention and Good Housekeeping in Municipal Operations					
6-1	Sensitive Areas	Director of Public Works	Identify and map sensitive areas	In compliance.	No activity planned.
6-2	Clean catch basins	Director of Public Works	Clean catch basins every other year, maintain records	Cleaned approximately 75% of catch basins town-wide in 2009.	Continue to clean catch basins yearly.
6-3	Sweep Streets twice per year	Director of Public Works	Sweep each street twice per year.	All streets were swept twice during permit Year 7 and as needed.	Continue to sweep each street twice per year and as needed.
6-4	Continue no pesticide policy	Director of Public Works	No pesticide use on Town property	No pesticides were used on Town property	Continue no pesticide policy
6-5	Tree survey	Director of Public Works / Tree Warden	Implement survey and long-term forestation plan	Limited staffing resources has eliminated the possibility of applying for tree survey grants through US Forestry. We are going to pursue utilizing a community service group to conduct the tree survey such as girl scouts or boy scouts.	Complete the survey and develop long term forestation plan.
6-6	Implement long-term forestation plan	Director of Public Works / Tree Warden	Implement long-term forestation plan	Planted 20 trees throughout Town	Continue to implement long-term forestation plan.
6-7	Provide training to DPW staff	Director of Public Works	Two training days per year	Presented stormwater videos to DPW staff.	Present training videos to DPW staff.
6-8	Implement long-term forestation plan	Director of Public Works / Tree Warden	Implement long-term forestation plan	In compliance	No activity planned.
6-9	Maintain covered salt storage; calibrate salt spreaders annually	Director of Public Works	Maintain salt storage shed, and calibrate salt spreaders, as needed	Calibrated salt spreaders in 2008. Awaiting available funding for salt storage shed improvement.	Improvement to salt storage shed over the next 3-4 years. Calibrate salt spreaders as needed.

Part IV. Summary of Information Collected and Analyzed

Television inspection

Approximately 15,000 LF of storm drains were television inspected between July and August 2004. Approximately 5,000 LF of underdrain and an additional 7,000 LF of storm drain were television inspected between March and October, 2008. The Town continues to focus on Stacey's Brook drainage area due to known contamination and an Administrative Consent Order issued by DEP in June 2008. Two remedies have been designed and will be implemented in Spring 2010 in the Banks and Farragut Roads area, and in the Columbia Street area. Construction will be funded through the SRF program.

Dry Weather Sampling

The Board of Health samples waters from local beaches on a regular basis during the summer.

DPW samples drainage outfall flow at King's Beach three times per week between May 1 and September 30 for total fecal coliform. Results are submitted to DEP as part of an Administrative Consent Order signed in June, 2008. These samples are representative of the water quality in Stacey's Brook and the associated drainage area.

Manhole Inspections

A select group of sewer manholes with underdrains were inspected in 2005 to identify the status of underdrain connections. A total of 41 manholes in subareas 2, 3A, 3B, 4 and 5A were inspected. Additional manhole inspections and underdrain television inspections were conducted in March - April 2008 to determine system interconnections. One contaminated underdrain connection to the drain was eliminated at Beach Avenue and Columbia Street, and investigations continue to detect other connections.

Beach Closings

During Permit Year 7, the following Swampscott beaches were closed: King's Beach once, Fisherman's Beach twice, Eisman's Beach once, and Preston Beach once. All closures followed significant rain events.