

### Errata for EDR v2.1 and v2.2 Structure Documents

Minor issues have been found and corrected in the EDR Structure Documents for both v2.1 and v2.2 since the posting of revised versions on December 22, 2005. Updated documents have been posted to correct the problems, as described below:

RT/Sec.	Change to the Instructions Document	EDR Document Applicability			
		v2.1 Redline- Strikeout	v2.1 Clean	v2.2 Redline- Strikeout	v2.2 Clean
532	For column 15, Duct Depth at Test Location, the Format (FTN) value was corrected to be F5.1. For column 26, Method of Determining WAF, the Format (FTN) was corrected to be A2.	*	*	*	*
617	For column 16, RATA End Date, the Length was corrected to be 8 and the Format (FTN) was corrected to be I8.	*	*	*	*