

**Table 7-6  
Montell USA (formerly Himont USA)  
Enforcement History by Contaminant**

<b>CHEMICAL</b>	<b>DATE</b>	<b>VIOLATION</b>	<b>OUTFALL</b>
Ammonia	8/4/87	Reported value of 26 lbs./day as in violation of the permit limit 260 lbs./day.	NOI
Ammonia	9/9/91	Reported value of 24.42 lbs./day was in violation of permit limit of 20 lbs./day.	NOI
Ammonia	1/7/92	Reported value of 66.6 lbs./day was in violation of the permit limit of 20 lbs./day.	NOI
Ammonia	1/28/92	Reported value of 17.3 lbs./day was in violation of the permit limit of 15 lbs./day.	NOI
Ammonia	1/28/92	Reported value of 0.77 lbs./day was in violation of the permit limit.	NOI
Ammonia	2/4/92	Reported value of 1.05 lbs./day was in violation of the permit limit.	NOI
Ammonia	2/11/92	Reported value of 0.91 lbs./day was in violaton of the permit limit.	NOI
Ammonia	2/18/92	Reported value of 0.87 lbs./day was in violation of the permit limit.	NOI
Ammonia	2/25/92	Reported value of 1.16 lbs./day was in violation of the permit limit.	NOI
Black Smoke	2/27/93	A release of black smoke occurred, causing intermittent heavy flaring over the duration of one hour, in violation of the permit.	NOI
Carbon	1/12/95	A release of approximately 1,500 lbs of carbon occurred over a druation of 79 minutes during a fire.	NOI
Carbon Dioxide	1/12/95	A release of 3,300 lbs. of carbon dioxide occurred over a duration of 79 minutes during a fire.	NOI
Carbon Monoxide	8/23/85	Reported release of 397 lbs. was in violation of the permit limit	NOI
Carbon Monoxide	1/12/95	A release of less than 5 lbs. of CO occurred over a duration of 79 minutes during a fire.	NOI
Chlorine	11/17/91	Reported release of 10 to 20 lbs. over approximately 1 hours was in violation of the permit limit.	NOI
Chlorine	6/10/94	Reported release of 15 lbs. of chlorine vapor for approximately 8 minutes was in violation of the permit limit.	NOI
Chromate	6/21/74	A release of an unkown quantity of chromate spilled and was in violation of permit limit.	NOI
HCL	6/9/88	Reported release of approximately 200 lbs. was in violation of the permit limit.	NOI
Hydrocarbon	8/25/85	Reported release of 48 lbs was in violation of the permit limit.	NOI
Isopropyl Alcohol	11/6/89	Reported value of 183 ppm was in violation of the permit limit.	002
Isopropyl Alcohol	10/14/91	A total of approximately 600 gallons (approximately 3,900 lbs) were spilled in Process Unit 3. Approximately 925 lbs. entered the Calcasieu River, while the remainder was successfully diverted.	NOI
Lubricating Oil	8/15/95	A release of approximately 100 lbs. of lubricating oil and 20 lbs of ammonia occurred over a duration of 10 seconds in violation of the permit limit.	002
NaOH	12/6/90	Reported release of 65 gallons of 4 wt % NAOH (22.7 lbs of NaOH) was in violation of the permit limit.	NOI
NaOH	2/8/92	Reported release of approximately 2,500 gallons of waste water, containing 50 lbs. of NaOH, was released into Calcasieu River in violation of the permit limit.	NOI

**Table 7-6  
Montell USA (formerly Himont USA)  
Enforcement History by Contaminant**

<b>CHEMICAL</b>	<b>DATE</b>	<b>VIOLATION</b>	<b>OUTFALL</b>
Nitrogen Oxides	8/23/85	Reported release of 181 lbs. was in violation of the permit limit.	NOI
Nitrogen Oxides	1/12/95	A release of less than 20 lbs. of nitrogen oxides occurred over a duration of 79 minutes during a fire.	NOI
Nonspecific	10/26/90	Reported release of 400 gallons of polymer stabilizer F-1031M was in violation of the permit limit. The release contained approximately 193 lbs. of calcium stearate (CAS No. 1592-23-0) and 637 lbs. of Irganox 1076 (CAS No. 2082-79-3). At least 75% of this material went through the surface drainage system, which is in violation of the permit.	NOI
Nonspecific	3/3/97	Aqueous Material - Approximately 700 gallons of aqueous stabilizer F-1031M entered the K-line chemical sewer and overflowed to the surface drainage system. The 700 gallons of diluted F-1031M contained and estimated 244 lbs of calcium stearate (CAS No. 1592-23-0) and 807 lbs. of Irganox 1076 (CAS No. 2082-79-3).	NOI
Not Specified	5/19/85	The facility was in violation for failing to notify the Air Quality Division regarding an upset within the required period of time.	NOI
Not Specified	10/91	The facility was in violation for failure to submit data for the parameters identified in Part III of the order for the month of October 1991.	NOI
Not Specified	8/13/92	The facility was in violation for the reporting requirements in that the Permittee had failed to submit data for the parameters identified in Part III for the months of October and November, 1991.	NOI
Not Specified	6/28/93	The facility was in violation for failing to plug or cap 8 valves.	NOI
Not Specified	94	The facility violated AQD regulations four times. No other information provided.	NOI
Oil and Grease	3/17/86	Reported value of 16.7 was in violation of the permit limit of 55 mg/L.	NOI
Oil and Grease	3/19/86	Reported value of 1.0 was in violation of the permit limit. No units were indicated.	NOI
Oil and Grease	5/12/89	The facility was in violation for failure to properly transfer samples.	NOI
Oil and Grease	6/16/93	Reported value of 119 mg/L was in violation of the permit limit of 15 mg/L.	NOI
Oil and Grease	6/18/93	Reported value of 16 mg/l was in violation of the permit limit of 15 mg/L.	NOI
Oil and Grease	6/19/93	Reported value of 16 mg/l was in violation of the permit limit of 15 mg/L.	NOI
Particulate	8/23/85	Reported release of 134 lbs was in violation of the permit limit.	NOI
PCBs	10/27/81	The facility was in violation for failure to mark one heat transfer system with "ML PCB" label.	NOI
PCBs	10/27/81	The facility was in violation for failure to test two heat transfer systems containing 1,500 gallons of fluid.	NOI
PCBs	10/27/81	The facility was in violation for improper disposal of PCBs.	NOI
pH	12/90	Reported value of 9.8 was in violation of the permit limit of 9.0.	NOI
pH	9/25/91	The facility was in violation for failure to provide a continuous record of the pH and temperature.	NOI
pH	2/8/92	Reported value of 9.8 was in violation of the permit limit of 9.0.	NOI
pH	6/15/92	Reported value of 9.5 was in violation of the permit limit of 9.0.	NOI

**Table 7-6  
Montell USA (formerly Himont USA)  
Enforcement History by Contaminant**

<b>CHEMICAL</b>	<b>DATE</b>	<b>VIOLATION</b>	<b>OUTFALL</b>
pH	6/16/92	Reported value of 9.5 was in violation of the permit limit of 9.0.	NOI
pH	6/17/92	Reported value of 9.5 was in violation of the permit limit of 9.0.	NOI
pH	7/15/92	Reported value of 9.5 was in violation of the permit limit of 9.0. The pH excursion occurred approximately 115 minutes.	NOI
pH	6/1/93	The facility was in violation for allowing the temperature and pH chart to be improperly changed, which resulted in a recording not being made for approximately 13 hours.	NOI
pH	6/4/93	Reported value of 9.7 was in violation of the maximum permit limit of 9.0.	NOI
pH	6/5/93	Reported value was in violation of permit limit. No other information provided.	NOI
pH	11/14/93	Reported value of 9.8 was in violation of the permit limit of 9.0.	NOI
pH	1/8/94	The facility was in violation for failure to properly record continuously.	NOI
pH	8/15/95	Reported value of 9.8 was in violation of the maximum permit limit of 9.0.	NOI
pH	4/16/96	Reported value was in violation of the maximum permit limit of 9.0.	NOI
pH	12/7/96	Reported value was in violation of the maximum permit limit of 9.0.	NOI
pH	2/7/98	Reported value was in violation of the maximum permit limit of 9.0.	NOI
Polyethylene	8/25/97	A release of less than 100 lbs occurred over a duration of 15 minutes in violation of the permit limit.	NOI
Polypropylene Pellets	7/23/90	Reported release of several thousand pounds of polypropylene pellets overflowed a retaining wall on the west side of facility and entered a ditch that flowed into Bayou d'Inde.	NOI
Polypropylene Pellets	7/24/90	Reported value was in violation of the permit limit.	NOI
Polypropylene Pellets	10/5/90	Reported release of polypropylene pellets in other than trace amounts as in violation of permit limits.	NOI
Polypropylene Pellets	1/12/98	Reported value of 300 lbs was in violation of the permit limit.	NOI
Propylene	6/2/93	The facility was in violation when an electrical failure at the propylene storage area caused J & K lines to shut down for several hours.	NOI
Propylene	1/8/94	Reported release of 80 lbs. of propylene occurred over a duration of 30 minutes.	NOI
Smoke	5/19/85	A release of an unknown quantity of heavy black smoke occurred over a 2-day period when the unit was being depressurized.	NOI
Smoke	5/25/85	A release of an unknown quantity of smoke occurred over a duration of 15 minutes.	NOI
Smoke	5/27/98	A release of an unknown quantity of smoke occurred over a duration of 40 minutes in violation of the permit limit.	001
Various	9/1/90	The facility was in violation for failure to properly monitor the temperature and pH chart at Outfall 001, for approximately 13 hours, in violation of the permit limit.	NOI
Various	10/23/92	The facility was in violation for various leaking components.	NOI
Various	1/19/93	The facility was in violation for various leaking components.	NOI
Various	6/14/93	The facility was in violation for leaking components.	NOI
Various	10/1/93	The facility was in violation for leaking components.	NOI

**Table 7-6**  
**Montell USA (formerly Himont USA)**  
**Enforcement History by Contaminant**

<b>CHEMICAL</b>	<b>DATE</b>	<b>VIOLATION</b>	<b>OUTFALL</b>
Various	4/5/94	The facility was in violation for leaking components.	NOI
Various	9/26/94	A release of less than 10 lbs. of a polymer dust occurred over a duration of 23 hours.	NOI
VOC	8/8/92	The facility was in violation for failing to plug or cap 2 valves.	NOI

NOI - No Outfall Identified