

DOCUMENTATION OF ENVIRONMENTAL INDICATOR DETERMINATION
RCRA Corrective Action
Environmental Indicator (EI) RCRIS code (CA725)
Current Human Exposures Under Control

Facility Name: St. Marys Metal Finishing
Facility Address: 1057 Trout Run Road, St. Marys, PA 15857
Facility EPA ID #: PAD046771374

1. Has **all** available relevant/significant information on known and reasonably suspected releases to soil, groundwater, surface water/sediments, and air, subject to RCRA Corrective Action (e.g., from Solid Waste Management Units (SWMU), Regulated Units (RU), and Areas of Concern (AOC)), been **considered** in this EI determination?

- If yes - check here and continue with #2 below.
- If no - re-evaluate existing data, or
- if data are not available, skip to #8 and enter "IN" (more information needed) status code.

BACKGROUND

Definition of Environmental Indicators (for the RCRA Corrective Action)

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EI developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Current Human Exposures Under Control" EI

A positive "Current Human Exposures Under Control" EI determination ("YE" status code) indicates that there are no "unacceptable" human exposures to "contamination" (i.e., contaminants in concentrations in excess of appropriate risk-based levels) that can be reasonably expected under current land- and groundwater-use conditions (for all "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action program the EI are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA). The "Current Human Exposures Under Control" EI are for reasonably expected human exposures under current land- and groundwater-use conditions ONLY, and do not consider potential future land- or groundwater-use conditions or ecological receptors. The RCRA Corrective Action program's overall mission to protect human health and the environment requires that Final remedies address these issues (i.e., potential future human exposure scenarios, future land and groundwater uses, and ecological receptors).

Duration / Applicability of EI Determinations

EI Determinations status codes should remain in RCRIS national database ONLY as long as they remain true (i.e., RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

Current Human Exposures Under Control
Environmental Indicator (EI) RCRIS code (CA725)

2. Are groundwater, soil, surface water, sediments, or air **media** known or reasonably suspected to be **“contaminated”**¹ above appropriately protective risk-based “levels” (applicable promulgated standards, as well as other appropriate standards, guidelines, guidance, or criteria) from releases subject to RCRA Corrective Action (from SWMUs, RUs or AOCs)?

	<u>Yes</u>	<u>No</u>	<u>?</u>	<u>Rationale / Key Contaminants</u>
Groundwater	X			TCE concentrations above MCL
Air (indoors) ²		X		TCE is below non-residential screening level
Surface Soil (e.g., <2 ft)		X		No Releases to surface soil documented
Surface Water		X		No releases to surface water documented
Sediment		X		No Releases documented
Subsurf. Soil (e.g., >2 ft)		X		Naturally occurring (arsenic and chromium)
Air (outdoors)		X		No releases documented

- If no (for all media) - skip to #6, and enter “YE,” status code after providing or citing appropriate “levels,” and referencing sufficient supporting documentation demonstrating that these “levels” are not exceeded.
- If yes (for any media) - continue after identifying key contaminants in each “contaminated” medium, citing appropriate “levels” (or provide an explanation for the determination that the medium could pose an unacceptable risk), and referencing supporting documentation.
- If unknown (for any media) - skip to #6 and enter “IN” status code.

Rationale and Reference(s):

Background

The St. Marys Metal Finishing (SMMF) facility has been in operation at its present location since 1971. SMMF is an active metal treatment facility that applies functional plating on small parts for industrial and automotive applications. In the past, the SMMF facility utilized trichloroethene (TCE) as a still rinse for impregnated parts. The spent TCE was disposed offsite. There have been no reported releases or remedial actions at the SMMF facility. Data from eight soil borings and four monitoring wells were collected in 2002. The soils samples were analyzed for volatile organic compounds (VOCs), polynucleated aromatic hydrocarbons (PAHs), and RCRA metals. Groundwater samples were analyzed for VOCs, PAHs, and dissolved RCRA metals.

Soil:

Subsurface soil samples were collected. Arsecic was detected in soil samples at concentrations from 5.57 mg/kg to 19.4 mg/kg, above the EPA Region 3 screening level for industrial soil of 3 mg/kg, however, below the Pennsylvania average background concentration of 23 mg/kg. Chromium was detected in soil samples at concentrations from 11 mg/kg to 26.5 mg/kg around the facility and higher in upgradient samples. Therefore, it is reasonable to conclude that the presences of arsenic and chromium in subsurface soil at the facility are naturally occurred.

Groundwater

TCE was detected in groundwater samples at concentrations as high as 12 ug/l, above the MCL of 5 ug/l.

Indoor Air

Due to the presence of TCE in the groundwater, a vapor intrusion pathway was evaluated in accordance with the EPA’s Subsurface Vapor Intrusion Guidance. EPA determined that the TCE level of 12 ug/l in groundwater would yield a

predicted indoor air concentration below the EPA's non-residential indoor air regional screening level. Since the property is currently used for industrial purpose, there are currently no acceptable risks to human health via vapor intrusion pathway.

Footnotes:

¹ "Contamination" and "contaminated" describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriately protective risk-based "levels" (for the media, that identify risks within the acceptable risk range).

² Recent evidence (from the Colorado Dept. of Public Health and Environment, and others) suggest that unacceptable indoor air concentrations are more common in structures above groundwater with volatile contaminants than previously believed. This is a rapidly developing field and reviewers are encouraged to look to the latest guidance for the appropriate methods and scale of demonstration necessary to be reasonably certain that indoor air (in structures located above (and adjacent to) groundwater with volatile contaminants) does not present unacceptable risks.

**Current Human Exposures Under Control
Environmental Indicator (EI) RCRIS code (CA725)**

3. Are there **complete pathways** between “contamination” and human receptors such that exposures can be reasonably expected under the current (land- and groundwater-use) conditions?

Summary Exposure Pathway Evaluation Table

Potential **Human Receptors** (Under Current Conditions)

<u>“Contaminated” Media</u>	Residents	Workers	Day-Care	Construction	Trespassers	Recreation	Food ³
Groundwater	No	No	No	Yes			No
Air (indoors)							
Soil (surface, e.g., <2 ft)							
Surface Water							
Sediment							
Soil (subsurface e.g., >2 ft)							
Air (outdoors)							

Instructions for Summary Exposure Pathway Evaluation Table:

1. Strike-out specific Media including Human Receptors’ spaces for Media which are not “contaminated” as identified in #2 above.
2. enter “yes” or “no” for potential “completeness” under each “Contaminated” Media -- Human Receptor combination (Pathway).

Note: In order to focus the evaluation to the most probable combinations some potential “Contaminated” Media - Human Receptor combinations (Pathways) do not have check spaces (“___”). While these combinations may not be probable in most situations they may be possible in some settings and should be added as necessary.

- If no (pathways are not complete for any contaminated media-receptor combination) - skip to #6, and enter “YE” status code, after explaining and/or referencing condition(s) in-place, whether natural or man-made, preventing a complete exposure pathway from each contaminated medium (e.g., use optional Pathway Evaluation Work Sheet to analyze major pathways).
- If yes (pathways are complete for any “Contaminated” Media - Human Receptor combination) - continue after providing supporting explanation.
- If unknown (for any “Contaminated” Media - Human Receptor combination) - skip to #6 and enter “IN” status code.

Rationale and Reference(s):

TCE was detected in groundwater samples at low concentrations above the MCL. There are no onsite groundwater users. Public water supply is provided by the St. Marys Area Joint Municipal Water Authority (SMAJWA). The facility is bounded to the north by W&H Machine shop, to the west by Stackpole Corporation/Carbone of America, to the south and east by vacant land. The groundwater flow direction is to the west of the facility because of the operation of the groundwater recovery wells at the Stackpole facility. Potential exposure of contaminated groundwater to construction workers may occur thru direct contact.

There are 3 domestic wells located within 0.5 mile radius of the facility. Due to the low levels of TCE in the groundwater and due to the operation of the groundwater recovery wells at Stackpole, it is reasonable to predict that TCE could not migrate to these domestic wells.

³ Indirect Pathway/Receptor (e.g., vegetables, fruits, crops, meat and dairy products, fish, shellfish, etc.)

**Current Human Exposures Under Control
Environmental Indicator (EI) RCRIS code (CA725)**

4. Can the **exposures** from any of the complete pathways identified in #3 be reasonably expected to be **“significant”**⁴ (i.e., potentially “unacceptable” because exposures can be reasonably expected to be: 1) greater in magnitude (intensity, frequency and/or duration) than assumed in the derivation of the acceptable “levels” (used to identify the “contamination”); or 2) the combination of exposure magnitude (perhaps even though low) and contaminant concentrations (which may be substantially above the acceptable “levels”) could result in greater than acceptable risks)?
- If no (exposures can not be reasonably expected to be significant (i.e., potentially “unacceptable”) for any complete exposure pathway) - skip to #6 and enter “YE” status code after explaining and/or referencing documentation justifying why the exposures (from each of the complete pathways) to “contamination” (identified in #3) are not expected to be “significant.”
 - If yes (exposures could be reasonably expected to be “significant” (i.e., potentially “unacceptable”) for any complete exposure pathway) - continue after providing a description (of each potentially “unacceptable” exposure pathway) and explaining and/or referencing documentation justifying why the exposures (from each of the remaining complete pathways) to “contamination” (identified in #3) are not expected to be “significant.”
 - If unknown (for any complete pathway) - skip to #6 and enter “IN” status code

Rationale and Reference(s):

TCE was detected in groundwater at low levels and the construction workers are protected by PPE. The exposure to contamination in the groundwater cannot be reasonably expected to be significant.

⁴ If there is any question on whether the identified exposures are “significant” (i.e., potentially “unacceptable”) consult a human health Risk Assessment specialist with appropriate education, training and experience.

**Current Human Exposures Under Control
Environmental Indicator (EI) RCRIS code (CA725)**

5. Can the “significant” exposures (identified in #4) be shown to be within **acceptable** limits?


- If yes (all “significant” exposures have been shown to be within acceptable limits) - continue and enter “YE” after summarizing and referencing documentation justifying why all “significant” exposures to “contamination” are within acceptable limits (e.g., a site-specific Human Health Risk Assessment).
- If no - (there are current exposures that can be reasonably expected to be “unacceptable”)- continue and enter “NO” status code after providing a description of each potentially “unacceptable” exposure.
- If unknown (for any potentially “unacceptable” exposure) - continue and enter “IN” status code.

Rationale and Reference(s):


**Current Human Exposures Under Control
Environmental Indicator (EI) RCRIS code (CA725)**

6. Check the appropriate RCRIS status codes for the Current Human Exposures Under Control EI (event code CA725), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (attach appropriate supporting documentation as well as a map of the facility).

- YE - Yes, "Current Human Exposures Under Control" has been verified. Based on a review of the information contained in this EI Determination, "Current Human Exposures" are expected to be "Under Control" at the St. Marys Metal Finishing, Inc. facility, EPA ID # PAD046771374, located at 1057 Trout Run Road, St. Marys, Pennsylvania 15857 under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.
- NO - "Current Human Exposures" are NOT "Under Control."
- IN - More information is needed to make a determination.

Completed by (signature) 
(print) Tran Tran
(title) RCRA Project Manager

Date 9-29-14

Supervisor (signature) 
(print) Paul Gotthold
(title) Associate Director
EPA Region 3

Date 9-29-14

Locations where References may be found:

US EPA Region III
Land & Chemicals Division
1650 Arch Street
Philadelphia, PA 19103

Contact telephone and e-mail numbers

(name) Tran Tran
(phone #) 215-814-2079
(e-mail) tran.tran@epa.gov