

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Abington, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA62-09_2008	Beaver Brook	Taunton	5			0.8	6.8		
								Pathogens	
MA62-33_2008	Shumatuscacant River	Taunton	5			3.9	8.5		
								Organic enrichment/Low DO	
								Other habitat alterations*	
								Pathogens	
								Siltation	
MA94-03_2008	French Stream	South Coastal	5			0.3	6.1		
								Cause Unknown	
								Nutrients	
								Organic enrichment/Low DO	
								Pathogens	
								Unknown toxicity	
MA62042_2008	Cleveland Pond	Taunton	4c	96.15	96.42				
MA62056_2008	Cushing Pond	Taunton	4c	5.73	5.73				
MA62094_2008	Island Grove Pond	Taunton	5	30.8	30.8				
								Noxious aquatic plants	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Abington, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		

Turbidity

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL