

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Cohasset, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA94-18_2008	Bound Brook	South Coastal	5			1.2	2.2	Flow alteration* Turbidity	
MA94-28_2008	Aaron River	South Coastal	5			1.0	1.0	Exotic species* Flow alteration* Noxious aquatic plants	
MA94-29_2008	Herring Brook	South Coastal	4c			0.3	0.3		
MA94-01_2008	Cohasset Harbor	South Coastal	5	1.45	445.22			Pathogens	
MA94178_2008	Aaron River Reservoir	South Coastal	4c	122.92	136.13			Flow alteration* Mercury	NEHgTMDL
MA94179_2008	Lily Pond	South Coastal	5	50.5	50.5			Flow alteration* Turbidity	
MA94-19_2008	The Gulf	South Coastal	5	53.95	80.56			Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Cohasset, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles	Cause	TMDL
				In Town - Total	Total	In Town - Total		
MA94-20_2008	Little Harbor	South Coastal	4a	153.89	153.89		Pathogens	CN120.0
MA94-32_2008	Cohasset Cove	South Coastal	5	1.25	55.46		Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries