

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Dalton, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
<i>MA11-15_2008</i>	South Brook	Hoosic	2			1.4	4.1		
<i>MA21-01_2008</i>	East Branch Housatonic River	Housatonic	5			3.5	11.3	Pathogens PCBs	
<i>MA21-02_2008</i>	East Branch Housatonic River	Housatonic	5			2.0	8.0	Pathogens Priority organics	
<i>MA21-08_2008</i>	Cleveland Brook	Housatonic	2			1.5	1.9		
<i>MA21-10_2008</i>	Anthony Brook	Housatonic	3			2.6	2.6		
<i>MA21-11_2008</i>	Wahconah Falls Brook	Housatonic	5			3.0	3.4	Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries