

Summary of Waterbody Assessment and TMDL Status in Massachusetts

West Boylston, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA51-17_2008	Poor Farm Brook	Blackstone	3			1.8	4.4		
MA81-24_2008	Gates Brook	Nashua	5			3.4	3.4	Cause Unknown Pathogens	
MA81-25_2008	Scarletts Brook	Nashua	5			0.5	0.5	Pathogens	
MA81-27_2008	Malden Brook	Nashua	2			1.9	1.9		
MA81-28_2008	Muddy Brook	Nashua	5			0.8	0.8	Cause Unknown	
MA81-32_2008	Quinapoxet River	Nashua	4c			1.2	7.9		
MA81147_2008	Wachusett Reservoir	Nashua	4a	636.64	3966.55			Mercury	NEHgTMDL

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries