

Table 1: Air Sampling Results, W.R. Grace Site, Hamilton Township, New Jersey

ADDI Warehouse Fire Emergency Response

April 19, 2005

Asbestos Analysis of Air Samples by Transmission Electron Microscopy via NIOSH Method 7402

All samples collected by EPA and EPA contractor personnel

Sample Number	Location Description	Analytical Result [fibers/cc]
Off-Site Locations (up to 2 miles from site):		
WRG-ER-01	Slackwood Firehouse	<0.002
WRG-ER-02	Colonial Lakes Park	<0.002
WRG-ER-03	Amherst Park (off Sandalwood)	<0.002
WRG-ER-04	Whitehead Park (between 4th and 5th Ave)	<0.002
WRG-ER-05	Enterprise Firehouse (Klockner Rd.)	<0.002
WRG-ER-06	Hamilton Municipal Building (Greenwood Ave.)	<0.002
WRG-ER-07	Mercerville Fire Co. (Nottingham Way)	<0.002
WRG-ER-08	AMC Movie Theaters (Sloan Rd.)	<0.002
On-Site Locations:		
WRG-ER-09	North of Building (Hamilton Transit Lot)	<0.002
WRG-ER-10	West of Building (Hamilton Transit Lot)	<0.002
WRG-ER-11	Northeast of Building (Amtrak Milham Yard Lot)	<0.002
WRG-ER-12	Northeast of Building (Amtrak Milham Yard Lot), Duplicate Sample for WRG-ER-11	<0.002
WRG-ER-13	East of Building (Amtrak Milham Yard Lot)	<0.002
WRG-ER-14	Southeast of Building (MLB Lot)	<0.002
Sample Number	Location Description	Analytical Result [fibers/filter]
WRG-ER-LB	Lot Blank Sample	0
WRG-ER-FB1	Field Blank Sample	0
WRG-ER-FB2	Field Blank Sample	0

cc: cubic centimeter