

Table 1
Disapproval of Delisted Dissolved Oxygen Impairment based on New Water Quality Standard Change

Assessment Unit			Segment Category
ID	Name	Reason and Explanation for Removal	
IL_AJF-16	Cedar Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	2
IL_ND-13	Crab Orchard Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	2
IL_IXM-04	Cypress Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	2
IL_IXF-01	Mill Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	2
IL_G-39	DesPlaines R.	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_RTZG	Duck	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_D-32	Illinois R.	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_LDDC	Markham Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_JMAA-01	Prairie Du Pont Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_RNB	Rend	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_ROR	Salem	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_GL-09	Salt Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_GL-10	Salt Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_OI-05	Shoal Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	5
IL_ATHG-05	Sugar Cr.	Cause deleted. WQS attained; reason for recovery unspecified.	5

Segment Category identifies where IEPA placed the waterbody after there action. All waterbodies are being place into Category 5 by USEPA