Page 1 of 2

2 100001

# United States Environmental Protection Agency Region IV POLLUTION REPORT

SITE: ande	Env	#1
BREAK:		
OTHER:		

- Date:Wednesday, September 12, 2007From:James Webster, OSC
- To: Matt Taylor, USEPA R4, ERRB, Emergency Response Section Chief

Subject: Initiation of Action Circle Environmental #1 170 5th Ave SW, Dawson, GA Latitude: 31.7731 Longitude: -84.4478

		A4RC
/2007 1	<b>Response Authority:</b>	CERCLA
)/2007 ]	Response Type:	Emergency
I	NPL Status:	
R000005439	Incident Category:	Removal Action
	Contract #	
)	EP07 - 12SEP07 /2007 /2007 R000005439	/2007Response Authority:/2007Response Type:NPL Status:

## Site Description

On September 7, 2007, GAEPD investigated several locations that contained abandoned drums and waste in Dawson, GA. GAEPD was alerted by City of Dawson and Terrel County personnel. Several residents in the area had complained of an odor. GAEPD's investigation found that a company called Circle Environmental had been evicted from two properties leaving behind waste in drums and a connex box. The property located on 170 5th AVE is a warehouse in the middle of downtown Dawson. On September 10, 2007, EPA R4's Phone Duty Officer dispatched OSC Webster to assess the situation.

## **Current Activities**

The OSC's assessment found metal drums containing hazardous labels thrown in piles outside of the warehouse. Because of the odor complaints, the OSC conducted air monitoring inside the warehouse and found elevated volatile organic compounds (VOC) levels. The levels were high enough that it required the use of Level B respiratory protection while performing the assessment. Under an emergency action, the OSC requested services from EPA's START contractor (Tetra Tech) and ERRS contractor(WRS).

The START contractor assisted with the identification and documentation of the drums located inside and outside of the warehouse. Approximately 488 drums were found through out the site. The majority of the drums had material in them and some had labels indicating waste oil, TCE or flamable liquids. The drums were on pallets and they were stacked inside the warehouse.

ERRS contractor was tasked to move the drums, identify if they are empty and stage the ones containing material by waste stream/incompatibility. Empty drums were crushed and sent off for disposal.

10547546

https://www.epaosc.net/sites%5C3455%5Cfiles%5Ccircleenvironmental1\_polrep\_1.htm 10/11/2007

# 2 10 0002

### **Planned Removal Actions**

START will continue to provide air monitoring, document site activites and track drum information.

ERRS contractor will continue to stage drums, sample them, perform hazcatting of the samples and obtain waste samples for waste disposal purposes.

### **Key Issues**

There has been some interest from an Albany, GA Channel 10 News and they have reported on two occasions. OSC will meet with local government officials and update them on EPA's action.

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
ERRS - Cleanup Contractor	\$75,000.00	\$0.00	\$75,000.00	100.00%
RST/START	\$25,000.00	\$0.00	\$25,000.00	100.00%
Intramural Costs				
USEPA - Direct (Region, HQ)	\$5,000.00	\$0.00	\$5,000.00	100.00%
Total Site Costs	\$105,000.00	\$0.00	\$105,000.00	100.00%

### **Estimated Costs \***

\* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

www.epaosc.net/circleenvironmental1