

Site Briefing

SITE: BCX Facility
BREAK: 2.7
OTHER: v. 5

Site Name: BCX Tank Site

FPN/CPN: C04G12

Date: 10/27/04

Reporting Period: 10/28/04-11/03/04

GST Case Number: 039-04

GST PERSONNEL ON SITE : MST1 Jon Cotton

SITE LOCATION: 1903 East Adams Street Jacksonville, Fl

SITE MAP: □□□□□

BRIEF SUMMARY OF HAZARDS ON SITE:□□□□□

- 1.High Ambient Temperatures
- 2.Waste Oil Products
- 3.Insects and Pests
- 4.Working from elevations
- 5.□□□□□

CURRENT/COMPLETED ACTIONS:

Contractors continue utilizing vacuum trucks to remove oily sludge from AST's. Contractors used a high powered vacuum truck which creates 3000 cfv vice 1500 cfv, to move the heavier sludge. Different, more powerful vacuum truck continued to have difficulty moving heavy sludge from AST to truck. Loaded approx. 10k gallons of sludge. Contractors are creating a staging area to move sludge on-site from vacuum truck to storage boxes. The sludge will then be combined with mixing agent to create solid. The solid will be transported off site to land fill.

GST EQUIPMENT ON SITE:

1. Computer Kit # 20
- 2.Digital Camera Kit # 2
- 3.PHd Ultra #19300
- 4.□□□□□
- 5.□□□□□
- 6.□□□□□
- 7.□□□□□
- 8.□□□□□
- 9.□□□□□
- 10.□□□□□
- 11.□□□□□
- 12.□□□□□
- 13.□□□□□
- 14.□□□□□
- 15.□□□□□



10445654