



Community Update #95—Final Update Pompton Lakes Study Area Pompton Lakes, New Jersey

Pompton Lake Dredging/Restoration

Community Update

August 2018

EPA CLEANUP ACTIVITIES

Basic Site Information—2018

The scope of work in 2018 involved placement of the eco-layer in the Island Area and the ABD as well as site restoration. Hydraulic dredging, processing and off-site disposal of sediment containing mainly mercury and lead in a 36-acre area within Pompton Lake called the Acid Brook Delta (ABD) is complete. The work was performed by The Chemours Company FC, LLC., through its contractor, Severson Environmental Services with EPA/NJDEP oversight.

Further information/contacts:

Borough of Pompton Lakes

<http://www.pomptonlakesgov.com>

EPA Remedial Project Manager

Perry Katz

(212) 637-4426

katz.ira-perry@epa.gov

EPA Community Involvement Coordinator

Pat Seppi

(646) 369-0068

seppi.pat@epa.gov

EPA's 95th and final update is to inform the community of the progress of activities related to the dredging and restoration performed on the 36-acre portion of the Pompton Lake Study Area known as the Acid Brook Delta (ABD). Two other areas that comprise the Pompton Lake Study Area (Area A and the Island Area) were also dredged and restored.

Activities performed (week of August 20th):

- ◆ Completed restoration work associated with Island Area, Uplands Soil Areas, ABD shoreline and Acid Brook.
- ◆ Completed demobilization of equipment from the site.
- ◆ Lake turbidity/ perimeter air (dust) monitoring is complete as water work is complete and there is no impacted material on-site.
- ◆ Monitoring data posted at www.pomptonlakesworks.com/pompton-lake-project/environmental-monitoring

DREDGING/RESTORATION WORK IS NOW COMPLETE!!!

NOTES:

You will periodically see personnel on-site performing activities including: inspecting plants/fencing and making repairs, as needed; watering plants, as necessary; inspecting the site per permit requirements and installing water monitoring points in compliance with permit requirements and

PHOTOS: THE FIRST PHOTO IS A WEST TO EAST VIEW OF THE NEWLY INSTALLED WALKWAY ALONG LAKESIDE AVENUE. THE SECOND PHOTO SHOWS SOME OF THE NEWLY INSTALLED AMENITIES AND PLANTINGS IN ROTARY PARK.

WE THANK YOU FOR YOUR PATIENCE, SUPPORT AND COOPERATION DURING THE IMPLEMENTATION OF THIS PROJECT!!

EPA CONTINUES ITS PRESENCE AT BOROUGH HALL THURSDAYS FROM 10A.M. TILL 4P.M.

ENJOY THE UPCOMING POMPTON DAY FESTIVITIES!!