


- LEGEND**
- EXISTING MONITORING WELL (INSTALLED BY OTHERS)
 - EXISTING MONITORING WELL (INSTALLED BY DELTA)
 - MONITORING WELL (INSTALLED BY DELTA IN OCTOBER 2009)
 - NG NOT GAUGED
 - NM NOT MEASURED
 - GROUNDWATER CONTOURS
 - GROUNDWATER FLOW DIRECTION




GROUNDWATER ELEVATIONS MAP
MAY 2010

**FORMER MCCANDLESS
FUELS SITE**

2231 Delsea Drive
Franklinville, New Jersey

 <small>10 LIPPINCOTT LA. MT. HOLLY, NJ 08060 Tel. (856) 273-1009 Fax. (856) 273-1012 1-866-Remedi-8</small>	DESIGNED: JMM
	DETAILED: SGH
	CHECKED: JMM
SOURCE: DELTA FIGURE 3	DATE: 5/5/2017
FILE NAME: 18016_BaseGW	JOB NO.: 18016
FIGURE: 12A	



GROUNDWATER SAMPLING RESULTS MAP
POLYCHLORINATED BIPHENYLS
JUNE 2010

FORMER MCCANDLESS
FUELS SITE

2231 Delsea Drive
Franklinville, New Jersey



10 LIPPINCOTT LA. MT. HOLLY, NJ 08060
Tel. (856) 273-1009 Fax. (856) 273-1012
1-866-Remedi-8

DESIGNED:
JMM
DETAILED:
SGH
CHECKED:
JMM

SOURCE: DELTA
FIGURE 6
DATE:
5/5/2017

FILE NAME: 18016_DeltaSoil
JOB NO.: 18016
FIGURE:
12B

