


## Neponset River Watershed Water Quality Grades and Compliance Rates - Calendar Year 2020

Grade	Water Segment	Average Compliance Rate
A+	Turner Pond (Walpole)	98.6%
A+	Crack Rock Pond	97.3%
A+	Ganawatte Farm Pond	96.8%
A+	Willet Pond	96.1%
A-	Massapoag Brook	89.7%
A-	Mill Brook	89.5%
A-	East Branch	86.7%
A-	Beaver Brook	86.3%
A-	Steep Hill Brook	86.2%
B+	Spring Brook	81.8%
B	Mother Brook	79.8%
B	Upper Neponset River	76.8%
B	Mine Brook	76.0%
B	Ponkapoag Brook	75.7%
B-	Lower Neponset River	74.4%
B-	Beaver Meadow Brook	71.8%
B-	Pecunit Brook	70.6%



C+	Hawes Brook	69.3%
C	Traphole Brook	63.0%
C	Pine Tree Brook	62.1%
C-	Pequit Brook	58.4%
D+	Germany Brook	50.1%
D-	Purgatory Brook	45.0%
F	Unquity Brook	31.4%
F	Meadow Brook	24.1%

### Average Compliance Rates for Swimming and Boating Standards

<b>A</b>	<b>B</b>	<b>C</b>	<b>D</b>	<b>F</b>
100-86	85-71	70-56	55-40	39-0

▲ Monitoring Points

## 2020 Neponset River Watershed Report Card

(based on 2018-2020 bacterial data)

