

United States Environmental Protection Agency



ANNUAL CLASS II DISPOSAL/INJECTION WELL MONITORING REPORT

Name, Address, Phone and/or Email of Permittee

Benson Energy, LLC
 772 Champlin Hill Road
 Smethport, PA 16749
 bensonbrice@hotmail.com

State

Pennsylvania

County

McKean

WELL TYPE

- Brine Disposal
- Enhanced Recovery
- Hydrocarbon Storage

Locate well in two directions from nearest lines of quarter section and drilling unit

Surface Location

1/4 of 1/4 of Section Township Range

ft. from (N/S) Line of quarter section

ft. from (E/W) Line of quarter section.

✓ See attached well location plot

Latitude

Longitude

Permit or EPA ID Number

PA S2 R903 BMCK

API Number

37-083-55287

Full Well Name

Benson 6

INJECTION PRESSURE

TOTAL VOLUME INJECTED

TUBING -- CASING ANNULUS PRESSURE (IF SPECIFIED IN PERMIT)

MONTH, YEAR	MAXIMUM PSIG	BBL	MCF	MAXIMUM PSIG
Jan	340	91		
Feb	—	—		
March	340	94		
April	—	—		
May	290	70		
June	340	88		
July	—	—		
August	350	85		
September	320	90		
October	300	85		
November	340	81		
December	340	88		

Certification

I certify under the penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment. (Ref. 40 CFR § 144.32)

Name and Official Title (Please type or print)

Brice N. Benson, President

Signature

Date Signed

1-13-2023