


East Palestine Train Derailment - TAGA Route Map -



For more information, see
<https://www.epa.gov/east-palestine-oh-train-derailment>

On April 21, 2023 EPA's Trace Atmospheric Gas Analyzer (TAGA) bus performed air monitoring around the East Palestine Derailment Location, monitoring for n-Butyl Acrylate.

Of the 31858 real-time readings taken during the day, 100% of the readings were below site-specific mobile thresholds.

-  Derailment Location
-  TAGA Route



Prepared For: U.S. EPA Prepared By: U.S. EPA GIS Unit