East Palestine Train Derailment - TAGA Route Map - March 24, 2023 N-Pleasant-DS Acclure Ave E-Grant-St -W North Ave E-North-Ave W-Martin-St W Martin St E-Martin St W Clark St East Palestine W Main-St E-Main-St Pleasant Dr E-Palestine-Rd 1260 ft For more information, see 1.000 1.000 https://www.epa.gov/oh/east-palestine-ohiotrain-derailment-emergency-response Feet Jimtown

On March 24, 2023, EPA's Trace Atmospheric Gas Analyzer (TAGA) bus performed air monitoring around the East Palestine Derailment Location, monitoring for n-Butyl Acrylate.

Of the 26,337 real-time readings taken during the day, 100% of the readings were **below** site-specific mobile thresholds.



TAGA Route



Prepared For: U.S. EPA Prepared By: U.S. EPA GIS Unit